

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator ARCO OIL AND GAS COMPANY	8. Farm or Lease Name G. W. Toby
3. Address of Operator P. O. Box 1610 Midland, Texas 79702	9. Well No. 7
4. Location of Well UNIT LETTER <u>G</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>24S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Langlie Mattix 7 RQ-GB
15. Elevation (Show whether DF, RT, GR, etc.) 3311.9 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Prod csg, cmt, perf & treat</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD'd 7-7/8" hole 5:00 p.m. 2-10-87 @ 3850. Ran 93 jts 5-1/2", 15.5#, K-55, LTC csg.
Cmt'd @ 3850 w/550sx "H" w/6% gel followed by 250sx "H" Neat. Circ cmt to surface. RR 9:00 a.m. 2-11-87.
2-19-87 RUPU. RIH & tag PBD 3805. Run GR-CNL-CCL f/3805-2800 & GR-CC1 to surf.
Perf Seven Rivers & Queen f/3520-3792 (20 holes)
2-20-87 Acidized 3520-3792 w/1000 gals. Frac w/50,000 gals & 148,500# sd.
2-23-87 Swab test four days.
2-27-87 RIH w/CA. Install pumping equipment & electric lines.
3-4-87 Began pumping for test. In 24 hrs pmpd 31 BO, 86 BW, 35 MCF.
3-12-87 In 24 hrs pmpd 89BO, 10 BW, 112 MCF
3-19-87 Potential test. In 24 hrs pmpd 60 BO, 52 BW, 107 MCF.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kenn W. Gosnell 915-688-5672
TITLE Engr. Tech. DATE 3-27-87

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR TITLE DATE APR 1 1987

CONDITIONS OF APPROVAL, IF ANY: