


# ASE ROTARY TABLE

Flow line will have to be made  
to fit UNDER Rotary.



RECEIVED  
NOV 6 1987  
OCD  
HOBBS OFFICE

Rec'd 4-21-88  
113