


ASE ROTARY TABLE

Flow line will have to be made
to fit UNDER Rotary.



Application to Drill
Conoco Federal "A" Well No. 1
Highland Production Company