Submit 3 Copies to Appropriate District Office

State of New Mexico En , Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Type of Wall: Osa Ornean Dry-Hole	DISTRICT I P.O. Box 1980, Hobbs, NM 88240 P.O. Box 1980, Hobbs, NM 88240 P.O. Bo DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Me DISTRICT III 1000 Rio Brazos kd., Aziec, NM 87410 SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE	x 2088 exico 87504-2088 WELLS EPPEN OR PLUG BACK TO A	WELL API NO. 30 025 3053] 5. Indicate Type of Lease STATE FEE X 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name
Other Completed Operation Completed Operations Clearly state all pertinent details, and give pertinent dates, including animated date of starting any proposed Court	(FORM C-101) FOR SUCH PROPOSALS)	
Enron 011 & Gas Company 3. Address of Operator P. O. Box 2267, Midland, Texas 79702 4. Well Location Unit Letter F: 1650 Feet From The north Line and 1980 Feet From The West Line Section 11 Township 24S Range 35E NMPM Lea County 14. Delevation (Show whether DP, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 3/22/89 PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILLY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent detas, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 6554 to 6454 (OVER) Thereby cerest that the information behave the sease complete to the beat of my knowledge and belief. TILE PRODUCT AND THE PRODUCT	OIL GAS WELL OTHER D	ry-Hole	Hefner 11 Com.
P. O. Box 2267, Midland, Texas 79702 4. Well Location Unit Letter F: 1650 Feet From The north Line and 1980 Feet From The WeSt Line Section 11 Township 24S Range 35E NMFM Lea County 10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3429.8' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 3/22/89 PERFORM REMEDIAL WORK PLUG AND ABANDON GHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 6554 to 6454 (OVER) 1. Intended 1980 Feet From The WeSt Line Continue Section 11 Line and 1980 Feet From The WeSt Line SUBSEQUENT REPORT OF: 3/22/89 FERFORM REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent detaits, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 1312 to 13012 Spot 30 sack cmt plug from 6554 to 6454 (OVER) 1. Interview Continue Line Line West From The West Continue Line Line Line Line Line Line Line Lin			8. Well No.
Unit Letter F : 1650 Feet From The North Line and 1980 Feet From The West Line Section 11 Township 24S Range 35E NMPM Lea County 10. Elevations (Show whether DF, RKB, RT, GR, stc.) 3429.81 GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 3/22/89 PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT & CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datasis, and give pertinent datas, including estimated data of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 6554 to 6454 (OVER) Interpretation for State Line TIME Regulatory Analyst TIME Regulatory Analyst TIME PREVIOUS ANAME Betty Gildon TILEPRENE NO. 915/686-3	P. O. Box 2267, Midland, Texas 79702		
10. Elevation (Show whether DF, RXB, RT, GR, etc.) 3429.8 GL	_ · · · ·	Line and 1980	Feet From The West Line
10. Elevation (Shorw whether DP, RRB, RT, GR, stc.) 3429.8 'GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 3/22/89 PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT STEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datalits, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information laws to true and complete to the best of my knowledge and bolid. This spece for State Use) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: 3/22/89 REMEDIAL WORK COMMENCE DRILLING OPNS. ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT SCASING TEST AND CEMENT JOB ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT SCASING TEST AND CEMENT JOB ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT SCASING TEST AND CEMENT JOB ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT SCASING COMMENCE DRILLING OPNS. ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT SCASING COMMENCE DRILLING OPNS. ALTERING CASING COMENCE DRILLING OPNS. ALTERING CASING COMMENCE DRILLING OPNS. ALTERING COMMENCE AND ALTERING CASING	Township = . C		NMPM Lea County
Thereby centry that the information by the latter of the beat of my knowledge and belief. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 3/22/89	10. Elevation (Show w.	hether DF, RKB, RT, GR, etc.)	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 6554 to 6454 (OVER) I bereby certify that the information layer is true and complete to the best of my knowledge and belief. SIONATURE Regulatory Analyst TILLE Regulatory Analyst TILLE REGULATORY ANALYSE TELEPHONE NO. 915/686-3	11. Check Appropriate Box to India		eport, or Other Data
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 13112 to 13012 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 6554 to 6454 Cut & recovered 6504 feet of 7" casing. 5480 9 9 = 1024 ff Of FRAN 140 = 6 (OVER) The or Frant NAME Betty Gildon TELEPHONE NO. 915/686-3	NOTICE OF INTENTION TO:		
CASING TEST AND CEMENT JOB OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 13112 to 13012 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 6554 to 12125 Cut & recovered 6504 feet of 7" casing. 5480 9 9 9 - 1024 ff Spot 40 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information between is true and complete to the best of my knowledge and belief. Signature Regulatory Analyst TILE PHENNE NO. 915/686-3	PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinens details, and give pertinens dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 13112 to 13012 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12225 to 12125 Cut & recovered 6504 feet of 7" casing. Spot 40 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information bows is true and complete to the best of my knowledge and belief. Signature TITLE Regulatory Analyst TITLE Regulatory Analyst TELEPHONE NO. 915/686-3	TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mud Weight 9.2 Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 13112 to 13012 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Cut & recovered 6504 feet of 7" casing. 5480 9 9 7 = 1024 pt	PULL OR ALTER CASING	CASING TEST AND CE	MENT JOB
Spot 30 sack cmt plug from 13640 to 13540. Spot 30 sack cmt plug from 13112 to 13012 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12225 to 12125 Cut & recovered 6504 feet of 7" casing. Spot 40 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information laws is the and complete to the best of my knowledge and belief. SIGNATURE TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3	OTHER:	OTHER:	
Spot 30 sack cmt plug from 13112 to 13012 Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12225 to 12125 Cut & recovered 6504 feet of 7" casing. Spot 40 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information three is true and complete to the best of my knowledge and belief. SIGNATURE TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3	WORK SEE RULE 1103.	ails, and give pertinent dates, inclu	ding estimated date of starting any proposed
Spot 30 sack cmt plug from 12828 to 12728 Spot 30 sack cmt plug from 12225 to 12125 Cut & recovered 6504 feet of 7" casing. Spot 40 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information bave is true and complete to the best of my knowledge and belief. SIGNATURE TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3	Spot 30 sack cmt plug from 13640 to 13540).	
Spot 30 sack cmt plug from 12225 to 12125 Cut & recovered 6504 feet of 7" casing. Spot 40 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information between the best of my knowledge and belief. SIGNATURE TITLE Regulatory Analyst TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3	Spot 30 sack cmt plug from 13112 to 13012		
Cut & recovered 6504 feet of 7" casing. 5480 9 9 = 1024 ff Spot 40 sack cmt plug from 6554 to 6454 (OVER) Thereby certify that the information bowe is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Analyst TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3	Spot 30 sack cmt plug from 12828 to 12728	3	
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Regulatory Analyst TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3	Spot 30 sack cmt plug from 12225 to 12125	5	
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Regulatory Analyst TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3		5480 9 / 8	= 1024 ft Ofen Hose
TYPE OR PRINT NAME Betty Gildon Regulatory Analyst THE Regulatory Analyst THE Regulatory Analyst THE PHONE NO. 915/686-3	(OVER)		,
TYPE OR PRINT NAME Betty Gildon TELEPHONE NO. 915/686-3		ge and belief.	
(This space for State Use)		_ mræ _Regulatory A	nalyst 4/4/89
	TYPEOR PRINT NAME Betty Gildon		тецернюме NO. 915/686-37
ATRUVEU B I	(This space for State Use) APTROVED BY CANADA CONTROL CONTROL	OIL & GAS	INSPECTOR OF 17 1991

RECEIVED

Spot 45 sack cmt plug from 3881 to 3781 (DV tool at 3831').

Shot 45 sack cmt plug from 720 to 620

Spot 15 sack cmt plug from 33 to 3 feet.

30 sacks set in rathole & mouse.

Dry-hole marker installed; Rig released - P&A Complete on 3/24/89.