

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 30568
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	B. F. Harrison "B"
8. Well No.	2
9. Pool Name or Wildcat	WILDCAT WOLFCAMP

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter F : 1980 Feet From The NORTH Line and 1800 Feet From The WEST Line
Section 9 Township 23S Range 37E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3310' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: PA ELLENBURGER, COMPLETE WOLFCAMP ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-22-99: MIRU. TOH & LD RDS & PUMP.
11-23-99: NDWH. NUBOP. REL TAC. TIH W/BIT, CSG SCRAPER ON TBG TO 9970'.
11-24-99: TAG @ 10,054'. TIH W/CIBP & SET @ 10,030'. TIH W/CMT BAILER & DUMP 35' CMT ON TOP OF CIBP FOR NEW PBTD @ 9995'. TIH W/TBG OPEN ENDED TO 2498'.
11-29-99: TIH W/TBG TO 9896'. RU PUMP TRUCK. CIRC HLE W/350 BBLS 2% KCL WTR. TEST & CHART CSG FOR 30 MINS TO 500# FOR NMOCOD-OK.
11-30-99: TIH W/GR/CCL & LOG FR 7500-6000'. TIH W/PERF GUN & PERF WOLFCAMP FORM 7274-90, 7304-28, 7352-56, 7372-92. TIH W/PKR, SN ON TBG. PSA 7190'. RU PUMP TRUCK & TEST CSG & PKR TO 500#-OK.
12-01-99: PRESS BACKSIDE TO 500#-OK. ACIDIZE WOLFCAMP PERFS FR 7274-7392 W/5500 GALS 15% NEFE HCL. RU SWAB. FL @ 200'. END FL @ 2000'.
12-02-99: FL @ 2000'. REL PKR. KILL W/BACKSIDE FLUID. NOBOP. RESET PKR. NUWH. SWAB DRY @ 7190'.
12-03-99: FL @ 4700'. END FL @ 7000'.
12-04-99: FL @ 4500'. END FL @ 7000'.
12-06-99: FL @ 5000'. END FL @ 7000'.
12-07-99: RIG DOWN.
3-08-00: ON 24 HR OPT. FLOWING 2 BO, 3 BW, & 55 MCF. WOLFCAMP PERFS 7274-7392'.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 4/21/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____

DATE _____