

Submit 3 copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

| | |
|--|--|
| WELL API NO. | 3002531483 |
| 5. Indicate Type of Lease | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil / Gas Lease No. | |
| 7. Lease Name or Unit Agreement Name | WEST DOLLARHIDE DRINKARD UNIT |
| 8. Well No. | 115 |
| 9. Pool Name or Wildcat | DOLLARHIDE TUBB DRINKARD |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 3165' |

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter A : 121 Feet From The NORTH Line and 1309 Feet From The EAST Line
Section 5 Township 25S Range 38E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3165'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Acidize & Scale Squeeze ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-15-99: MIRU. BLED OFF WELL. POH W/RDS & PMP. LD BAD RDS. NDWH. NUBOP. TIH W/SONIC HAMMER TOON ON 186 JTS.
2-16-99: BLED WELL DN. TIH W/2 7/8" TBG. ACIDIZE PERFS W/3000 GALS 15% NEFE. SWAB BACK LOAD. TOH W/SONIC HAMMER TOOL & TIH W/MUD JT, SN, TBG & TAC. BTM @ 6865'. SN @ 6777'. TAC @ 6034'. NDBOP. FLANGE UP WH. RIG UP ROD EQPT.
2-17-99: BLED OFF WELL. TIH W/PUMP, GAS ANCHOR, SNKR BARS, & RDS. LOAD & TEST W/500 PSI. SPACE OUT & HANG ON BEAM.
2-21-99: SCALE SQUEEZE W/2 DRUMS TH793.
2-21-99: ON 24 HR OPT. PUMPED 51 BO, 94 BW, & 66 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 3/16/99

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS

APPROVED BY DISTRICT I SUPERVISOR TITLE

DATE MAR 8 1999

CONDITIONS OF APPROVAL, IF ANY: