Submit 3 conies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Chergy, Millerais and Matu	iai itt	esources Department	Revised 1	-1-89	
OIL CONSERVA	TIC	ON DIVISION	WELL ARINO	·	
O Salita Fe, New IVI	exico	0 0/304-2088	1	E 🗵	
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			•		
-101) FOR SUCH PROPOSAL	.S.)		WEST DOLLARHIDE DRINKARD UNIT		
OTHER					
N ODATION & BRODUSTION			8. Well No.		
TEXACO EXPLORATION & PRODUCTION INC. 3. Address of Operator 205 E. Pander LIORDS NM 99240			110		
r, HOBBS, NM 88240			1		
1119 Feet From The	NORT	TH Line and 2322	Feet From The WEST Line		
•		•			
10. Elevation (Show whether DF, RKB, RT,GR, etc.) GR-3137', KB-3155'					
	, i tac	1			
-	_	Su	BSEQUENT REPORT OF:		
PLUG AND ABANDON		REMEDIAL WORK	△ ALTERING CASING		
CHANGE PLANS		COMMENCE DRILLING OPE	RATION PLUG AND ABANDONMENT		
		CASING TEST AND CEMEN	T JOB 🔲		
		OTHER:	Acidize & Scale Squeeze	\boxtimes	
erations (Clearly state all pert	inent	details, and give pertinen	t dates, including estimated date of startin	ıg	
2-26-99: MIRU. JAR PUMP LOOSE. TOH W/RDS & PMP. PUMP 700 GALS 15% NEFE DN TBG & FLSH W/31 BBLS PROD WATER. SWAB BACK LOAD. TIH W/PUMP & RDS. CHANGED OUT 10 1" RDS DUE TO WEAR. HANG ON & LOAD & TEST. 3-01-99: RIG DOWN. 3-10-99: ON 24 HR OPT. PUMPED 19 BO, 88 BW, & 7 MCF. FINAL REPORT					
	P.O. BOY Santa Fe, New M CICES AND REPORTS ON POSALS TO DRILL OR TO DE RVOIR. USE "APPLICATION FINANCIAL ON THE PROPOSAL OTHER PLORATION & PRODUCTION OF, HOBBS, NM 88240 1119 Feet From The Depropriate Box to Indicate Oppropriate Box to Indicate Oppro	OIL CONSERVATION P.O. Box 208 Santa Fe, New Mexicon Santa Fe, New	TICES AND REPORTS ON WELL POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A RVOIR. USE "APPLICATION FOR PERMIT"101) FOR SUCH PROPOSALS.) OTHER PLORATION & PRODUCTION INC. T, HOBBS, NM 88240 1119 Feet From The NORTH Line and 2322 Township 25S Range 38E NM 10. Elevation (Show whether DF, RKB, RT,GR, etc.) GR-3137', Proportiate Box to Indicate Nature of Notice, Report N TO: PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OPE CASING TEST AND CEMEN OTHER: HW/RDS & PMP. PUMP 700 GALS 15% NEFE DN TBG & FLS OUT 10 1" RDS DUE TO WEAR. HANG ON & LOAD & TEST.	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088 Santa Fe, New Mexico 8. Indicate Type of Lease Santa Fe Fe Fe From The West Dellar British Fe Fe From The West Dellar British Fe Fe Fr	

I hereby certify that the information SIGNATURE	abor is true and complete to the best of my knowledge and belief. **TITLE** Engineering Assistant**	DATE <u>3/26/99</u>
TYPE OR PRINT NAME	J. Denise Leake	Telephone No. 397-0405
(This space for State Use)	ORIGINAL SIGNED BY CHOIC WILLIAMS	F. 1991
APPROVED BY	DIGHTAGT I SUPERITHER	DATE
CONDITIONS OF APPROV	/AL, IF ANY:	0.0