Submit 3 Copies to Appropriate District Office


State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I			
	OIL CONSI	ERVATION DIVISION	
O. Box 1980, Hobbs NM 88240 P.O. Box 2088 ISTRICT II Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-31514	
P.O. Drawer DD, Artesia, NM 8	88210 Santa re	e, New Mexico 8/504-2088	5. Indicate Type of Lease
DISTRICT III	4.87410		STATE X FEE
1000 Rio Brazos Rd., Aztec, NM	4 8/ 4 10		6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FO DIFFERENT	Y NOTICES AND REPOR FOR PROPOSALS TO DRILL OF TRESERVOIR. USE "APPLIO FORM C-101) POR SUCH PRO	OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT*	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL G	:40		WHITE FANG
WELL X	VELL (OTHER	
2. Name of Operator ARCO Permian			8. Well No.
3. Address of Operator P.O. Box 1710; Hobbs, Ne	esa Monico 88240 P.O. Bo	X 1085, EUNILL N.M. 8823.	Q. Pool come on Wildow
4. Well Location		Line and 950	
 -			
Section 30	Township 25S	Range 38E ion (Show whether DF, RKB, RT, GR, eu	NMPM LEA County
	(//////////////////////////////////////	KB	<i>Y////////////////////////////////////</i>
11. Chec	ck Appropriate Box	to Indicate Nature of Notic	e, Report, or Other Data
NOTICE O	OF INTENTION TO	: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND AB	ANDON REMEDIAL WORK	☐ ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLAN	NS COMMENCE DRILLI	ING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND	
)THER:		OTHER: TEMPOR	ARILY ABANDON
	eted Operations (Clearly state		
	leted Operations (Clearly state		ARILY ABANDON tes, including estimated date of starting any proposed
12. Describe Proposed or Compl			
 12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF 	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da	tes, including estimated date of starting any proposed
12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63:	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da	tes, including estimated date of starting any proposed
 12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF 	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da	tes, including estimated date of starting any proposed
 12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF 	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da	tes, including estimated date of starting any proposed
 12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF 	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da	tes, including estimated date of starting any proposed
 Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF 	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da	tes, including estimated date of starting any proposed
 Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF 	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da. ORMED 04/30/97. CHART AITA	tes, including estimated date of starting any proposed $CHED$
 12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF 	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da. ORMED 04/30/97. CHART AITA	tes, including estimated date of starting any proposed $CHED$
12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF	153' F CMT ON TOP, TA PERFY	all pertinent details, and give pertinent da. ORMED 04/30/97. CHART AITA	tes, including estimated date of starting any proposed $CHED$
12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF D; r X ^ 1 N F 1 F 1	F CMT ON TOP. TA PERFO Cold Administrative Assists	all pertinent details, and give pertinent da. ORMED 04/30/97. CHART ATTA	tes, including estimated date of starting any proposed CHED (a) Of Temporably
12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF D; r X ^ 1 N F 1 F 1	F CMT ON TOP. TA PERFO Cold Administrative Assists	all pertinent details, and give pertinent da. ORMED 04/30/97. CHART ATTA	tes, including estimated date of starting any proposed
TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF D; r X ^] N P F	stove is true and complete to the be	all pertinent details, and give pertinent da. ORMED 04/30/97. CHART ATTA	tes, including estimated date of starting any proposed CHED (a) Of Temporably
12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP @ 6175' W/35' OF D; r X ^] N	stove is true and complete to the be Kelli'e D	all pertinent details, and give pertinent da. ORMED 04/30/97. CHART ATTA	ches, including estimated date of starting any proposed CHED CHED An analy Date Kellie D. 5-9-9
12. Describe Proposed or Complwork) SEE RULE 1103. TD: 8925' PERFS: 6274-63: SET CIBP © 6175' W/35' OF D; r X ^] F [] I hereby certify that the information a SIGNATURE	stove is true and complete to the be Kelli'e D	This Approximate of my knowledge and belief. ITTLE 05/09/97 Adm	TELEPHONE NO. 505-394-1649

11/16

/,D



Received Hobbs OCD

WHITE PORTS A SENSONS