Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088	WELL API NO. 30-025-31538
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210  Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lesse No. 6313726
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name R. R. SIMS
1. Type of Well: OIL GAS WELL X WELL OTHER	
2. Name of Operator TEXACO EXPLORATION AND PRODUCTION INC.	8. Well No. 2
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	9. Pool name or Wildon TEAGUE FUSSELMAN, NORTH
4. Well Location  Unit Letter N : 660 Feet Prom The SOUTH Line and 1650 Feet Prom The WEST Line	
Section 4 Township 23-SOUTH Range 37-EAST NMPM LEA County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CE	
OTHER: OTHER: CASING TE	ST & DRILL OPEN HOLE X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
1. MIRU WELLTECH UNIT. CLEAN OUT CASING. TESTED CASING TO 1500# FOR 30 MINUTES 07-02-92.  2. PICKED UP DRILL COLLARS & TIH. TESTED CASING AND SURFACE EQUIPMENT TO 3000#. 07-06-92.  3. DRILLED 4 3/4 OPEN HOLE TO TD OF 8965'. 07-08-92.  4. HALLIBURTON RAN GR-CCL-CNL FROM 8965' TO SURFACE, PET\CBL FROM 8700' TO 3550', AND SONIC FROM 8700' TO 5400'.  5. WEDGE SET CIBP AT 8775' AND DUMPED 20' OF CEMENT ON TOP. NEW PBTD IS 8755'. 07-09-92.  6. WEDGE PERFED w/ 2 JSPF 7508'-10'. RAN TRACER SURVEY. INDICATED CHANNELING.  7. DOWELL SQUEEZED PERFS WITH 200 SACKS CLASS H w/ .5% D-60 @ 15.6ppg. 07-16-92.  8. CLEAN OUT CEMENT AND TESTED SQUEEZE TO 1500# FOR 30 MINUTES 07-18-92.  9. WEDGE PERFED w/ 2 JSPF: 7508-10, 7516, 7530-34, 7562-66, 7590-98. DEVONIAN TEST.  10. BREAK FORMATION WITH 200 GAL 15% NEFE SPOT ACID. SWAB 47 BLW IN 4 HOURS 07-20-92.  11. SWAB 5 BLW & 143 BW IN 12 HOURS 07-21-92.  12. WELL FLOWED 10 BNO IN 1 HOUR 07-22-92. DIED. TIH WITH 2 7/8 TUBING.  13. PREP TO RUN RODS AND PUMP TEST.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  C.P. Bashilm / Curt Title DRILLING OPERAT	IONS MANAGER DATE 07-23-92
TYPEOR PRINT NAME C. P. BASHAM	TELEPHONE NO. 915-688462
TITEOGRAPH NAME V. C. DAOI DAW	
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	JUL 28 92
APPROVED BY	DATE -