(November 1983) (Fornerly 9-331) DEPART	UNITED STATES 'MEN')F' THE INTERI AU OF LAND MANAGEMENT		Expires August 31, 1985 6. LEASE DESIGNATION AND SERIAL NO. LC-064118	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS COTHER OTHER			7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
Plains Petroleum Operating Company			E. C. Hill 'B' Federal	
3. ADDRESS OF OPERATOR			9. WELL NO.	
415 W. Wall, Suite 1000, Midland, TX 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			8 10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface			Teague (Blinebry)	
Unit 0, 800' FSL & 1980' FEL			11. SEC., T., B., M., OR BLE. AND	
0.1.0 0, 10.0 10.0 1.0.1			SURVEY OR AREA	
			Sec 34, T23S, R37E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF.	, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE	
30 025 31730	3253.2 GR		Lea NM	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO:			JENT REPORT OF:	
TEST WATER SHUT-OFF	PCLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*	SECOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL	CHANGE PLANS	(Other)	of multiple completion on Well	
(Other) Completion or Recompletion Report and Log form.)				
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *				
09-14-92 Spud 12-1/4" surface hole @ 8:45 p.m. Sitton Drilling.				
shoe, 1175 Prem	Drilling 7-7/8" hole. Run 28 jts 8-5/8" 24# J55 STC w/guide shoe/float collar & 10 centralizers (1206.43'). Set & cmt'd @ 1175'KB w/410 sx Premium Plus + 4% Gel + 2% CaCl ₂ . Tail w/200 sx Premium Plus + 2% CaCl ₂ . Bump plug @ 8:00 a.m. 09-16-92. Circulated 137 sx cmt to pit. WOC 9-1/2 hrs. Press up BOP for 60 min - held OK.			
15.5	Drilling 7-7/8" hole. Set & cement 109 jts 5-1/2" (6027.61') csg, 15.5# j-55 @ 6000'. Ran 20 centralizers. DV Tool - 4890', Marker Joint 5254'-5275'.			
O9-27-92 Cement 1st stage w/20 bbls FW, 250 sx Premium Plus C, 5#/sx salt. Displace 30 bbl FW + 112 bbls Mud (1 bbls over displacement). Did not bump plug. Float held. Drop bomb. Open DV tool & circulate csg. Circ 45 sx cement off 1st stage to pit. Cement 2nd stage w/20 bbls FW, 1400 sx HL C, 1/4#/sx Flocele, tail 100 sx Premium Plug C Neat displace w/117 BFW, bump plug w/3500#. Close DV tool. Float held. Circulate 170 sx cmt to pit. ND, jet pits, set slips. Cut csg & weld on bell nipple. Rig released @ 2:30 P.M. 9-27-92.				
SIGNED SIGNED	ν . ν	Office Mgr/Tech	DATE	
(This space for Federal or State office use)				
APPROVED BY	TITLE	Ade	DATE	
CONDITIONS OF APPROVAL, IF		29	1992	

RECEIVED
NOV 0 2 1992
OCD HOSSS OFF