State of New Mexico

Submit 3 copies

Ener Ainerals and Natural Resources Department Form C-103

District Office	America and Natur	ai iv	esources populations		Revise	d 1-1-89
DISTRICT I	OIL CONSERVA	TI	ON DIVISION	WELL API NO		 -
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088				30 025 31765		
DISTRICT II Santa Fo. New Meyico 87504-2088				5. Indicate T		
P.O. Box Drawer DD, Artesia, NM 88	210				STATE 🔀	FEE 🗌
DISTRICT III	10			6. State Oil /	Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 874		A/EI	1			
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Nan	ne or Unit Agreement Name	
DIFFERENT RESI	ERVOIR. USE "APPLICATION F	OR P		1	V. HB- FED. NCT-1	
011	(C-101) FOR SUCH PROPOSAL	3.)			5 / 25///5/ /	
1. Type of Well: OIL GA WELL WE						
Name of Operator TEXACO EXPLORATION & PRODUCTION INC.			8. Well No.	21		
				ZI		
3. Address of Operator 205 E. Bender, HOBBS, NM 88240			9. Pool Name			
4. Well Location				<u> RH</u>	ODES YATES SEVEN RIVERS	
Unit Letter:	1543' Feet From The	Sout	hLine and _1093'	Feet From 1	The East Line	
Onit Letter						
Section 27	Township26-S	F	Range <u>37-E</u> NM	IPM	LEA COUNTY	
	10. Elevation (Show whether D	F, R	(B, RT,GR, etc.) 2974' GI			
11					<u> </u>	
11. Check A	Appropriate Box to Indicate	Na	ture of Notice, Report	i, or Other I	Jata	
NOTICE OF INTENTION	ON TO:		SL	JBSEQUE	NT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	П	COMMENCE DRILLING OPE	RATION	PLUG AND ABANDONMENT	. П
		_	CASING TEST AND CEMEN	IT JOB		_
PULL OR ALTER CASING OTHER:		П	OTHER:	L	cidize	
any proposed work) SEE RULE 11 4/14/97: Miru. Toh w/rods and pump. N 4/15/97: Tih w/bulldog bailer and cleane w/500 psi. Acidize w/5000 gals 15% and 4/16/97: Toh w/pkr and tih w/2 7/8 tbg, t w/pump, gas anchor,& rods. Hang on be 4/17/97 thru 4-29-97: Testing 4/30/97 24 hrs 26 bo, 74 bw, 8 mcf OP	NU BOP. Tih w/bit and scraper and out from 3293 to 3330(27'). Tohed 3000# rock salt. Maximum Press tac, and 96 jts 2 7/8 tbg. Bottom of earn and POP. Rig down Dawson.	w/ba sure 3	ailer and tih w pkr, sn, 27/8 3800 psi, ISIP 1800 psi, 15 r	tbg and set pk nin 1500 psi, /	rat 3073. Load and test annuage rate 3.5 BPM.	
I hereby certify that the information above is true and com SIGNATURE TYPE OR PRINT NAME F		ingir	neering Assistant		DATE <u>5/8/97</u> Telephone No. 397-043	2
(This space for State Use) ORIGIA(A) CICAIC	D DV INDAV CEVYON					