

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	GEOLOGIC MARKERS		
				NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	1050					
Salado	1215					
Yates	2740					
Penrose	3392					
San Andres	3810					
Glorietta	4906					
Yeso	5013					
Tubb	5910					

RECEIVED

NOV 10 1955