

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002532172
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	HARRISON, B. F. - B -
8. Well No.	12
9. Pool Name or Wildcat	TEAGUE FUSSELMAN, NORTH
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3312', KB-3326'

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator  
205 E. Bender, HOBBS, NM 88240

4. Well Location  
Unit Letter C : 760 Feet From The NORTH Line and 2100 Feet From The WEST Line  
Section 9 Township 23-SO Range 37-EA NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: PB LOWER, PERF UPPER FUSSELMAN ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-14-99: MIRU. NDWH. NUBOP.  
6-15-99: TIH W/BIT, & CSG SCRAPER TO 8833'. TIH W/CIBP & SET @ 8806'. RU PUMP TRUCK & LOAD TEST CIBP TO 500#-OK. TIH W/PER GUN. PERF UPPR FUSSELMAN FR 8768-84.  
6-16-99: TIH W/TP, PKR, & SN ON 2 7/8" TBG. SET PKR @ 8617'. TP @ 8783'. INSTL STRIPPER. OPEN BY PASS ON PKR & SPOT 500 GALS 15% NEFE HCL ACR PERFS 8768-8784'. CLOSE BYPASS. RU SWAB. FL @ 700'. END FL @ 4400'.  
6-17-99: FL @ 1800'. END FL @ 3800'. REL PKR. TIH W/IPMA, SN, TBG, TAC. SET @ 14' KB. OPMA @ 8800'. SN @ 8769'. TAC @ 8605'. NDBOP. SET TAC. NUWH.  
6-18-99: TIH W/STRAINER NIPPLE, PUMP, RDS. TAG UP ON TIGHT SPOT @ 8562'.  
6-19-99: NDWH. NUBOP. REL TAC. TIH W/TBG. NDBOP. SET TAC. NUWH.  
6-21-99: TIH W/PMP, K-BARS, RDS. HANG WELL ON. PUMPING @ 5:00 PM. RIG DOWN.  
7-26-99: ON 24 HR OPT. PUMPED 27 BO, 334 BW, & 21 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 08/13/1999

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS:

APPROVED BY DISTRICT I SUPERVISOR TITLE

DATE

AUG 19 1999

CONDITIONS OF APPROVAL, IF ANY: