## Submit 3 copies to Appropriate District Office

## State of New Mexico

Form C-103 Revised 1-1-89

E ,y, Minerals and Natural Resources Department

<u>DISTRICT I</u>	OIL CONSERVAT	NOISIVIA NOIT	Tursu Apixio
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2		WELL API NO. 30 025 32223
<u>DISTRICT II</u>	Santa Fe, New Mex		5. Indicate Type of Lease
P.O. Box Drawer DD, Artesia, NM 88210	Canta i C, i tew iviez	X100 07 00+ 2000	STATE STATE
DISTRICT III  1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No.
r	TICES AND REPORTS ON W	WELL	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
			SIMS, G. W.
1. Type of Well: OIL GAS OTHER			
Name of Operator     TEXACO EXPLORATION & PRODUCTION INC.			8. Well No.
Address of Operator P.O. Box 46510, Denver Colorado 80201-6510			9. Pool Name or Wildcat
4. Well Location			
Unit Letter B:	510 Feet From The No	ORTH Line and 2230	Feet From The <u>EAST</u> Line
Section 9 Township 23-S Range 37-E NMPM LEA COUNTY			
	10. Elevation (Show whether DF, F	RKB, RT,GR, etc.) GR-3310'	, KB-3324'
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION	ON TO:	SI	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	CHANGE PLANS	COMMENCE DRILLING OP	ERATION PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMEI	<b></b>
OTHER:		OTHER:	COMPLETION - TUBB
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.</li> <li>UNION PERFED THE TUBB: 6098-6100, 6104-6106, 6109-6113, 6116-6120, 6123-6131, 6135-5137, 6144-6148, 6151-6156, 6160-6163, 6180-6186, 6188-6192, 6196-6202, 6204-6206, 6208-6216, 6218-6221, 6224-6233, 6242-6244. 148 HOLES.</li> <li>TEST TBG TO 5000 PSI. FISH STANDING VALVE. REVERSE ACID INTO TBG. SET PACKER &amp; TEST ANNULUS TO 3000 PSI. ND BOP &amp; NU FRAC TREE. 11-16-94.</li> <li>DOWELL UTILIZED 222 BALL SEALERS ON ACID BALLOUT. HAD GOOD ACTION. DOWELL ACIDIZED W/ 3700 GAL 15% HCL. 11-18-94. SAND FRAC DOWN 3.5" TBG W/ 40# XL GEL @ 35-40 BPM. DOWELL FRAC'D W/ 61000 GAL FLUID &amp; 203000 16/30 XL GEL SAND. 11-18-94.</li> <li>MIRUSU. RELEASE PKR &amp; PULL FREE 150 &amp; STUCK PKR. COULD NOT REVERSE CIRCULATE. CLOSE RAMS &amp; PUT 3000# ON BACKSIDE &amp; WORK STRING UP. BROKE CIRCULATION W/ PKR FREE. REVERSE 4-TBG CAP. PULL 9 STAND &amp; A SINGLE. 11-19-94.</li> <li>FINISH TOH LD 3.5" TBG. PICK UP NOTCH COLLAR &amp; 2.875" TBG &amp; TIH. TAG TOP OF SAND @ 5920. PULL 7 STANDS. 11-20-94.</li> <li>WASH OUT SAND DOWN TO TOP OF RBP @ 6344*: CIRCULATE HOLE CLEAN &amp; PULL UP HOLE TO 5507". 11-21-94.</li> <li>TOH &amp; PICK UP UNIV 16 K PKR &amp; TIH. SET PKR TEST BACKSIDE TO 1000 PSI. NU PROD. TREE &amp; START SWABBING WELL. SWABBED 93 BLW IN 2 HOURS. 11-22-94.</li> <li>FLOWED 7 BO, 50 BLW, 1097 MCFD, FTP 400, 20/64" CHOKE IN 24 HOURS. 11-25-94</li> </ol>			
I hereby certify that the information above is true and complete	0 /0 0 0	Orilling Operations Mgr.	DATE 4/42/05
	mara / Section 1	g = Ferminag.	DATE 1/13/95  Telephone No. (303)621-4851
TYPE OF PRINT NAME	C P Basham		relephone No. (303)021-4031

(This space for State Use)

OR SHEET STORE LEVEL TORY SEXTON

\_TITLE\_

DATE\_

JAN 23 1395