

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

NSL-3405

WELL API NO.

30-025-32535

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-1327

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

2. Name of Operator

OXY USA Inc.

16696

8. Well No.

264

3. Address of Operator

P.O. Box 50250 Midland, TX 79710

9. Pool name or Wildcat

37240

Langlie Mattix 7 Rvr O-G

4. Well Location

Unit Letter L : 1400 Feet From The South Line and 160 Feet From The West Line

Section 32 Township 23S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3305'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Completion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3900'


PBTD - 3638'

Perfs - 3453' - 3627'

SEE OTHER SIDE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE

Regulatory Analyst

DATE

4/27/95

TYPE OR PRINT NAME

David Stewart

915- TELEPHONE NO. 685-5717

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

MAY 02 1995

CONDITIONS OF APPROVAL, IF ANY:

ATTACHMENT C-103
OXY USA INC.
MYERS LANGLIE MATTIX UNIT #264
SEC 32 T23S R37E
LEA COUNTY, NM

MIRU PU 6/29/94, RIH & TAG CMT @ 3853', CHC, TEST CSG TO 1000#, HELD OK. POOH, RIH W/ CBL. PERF PENROSE W/ 2SPF @ 3650-54, 64-81, 86-92, 3696-3705, 32-39, 83-3787, 3804-09, 25-3829' TOTAL 128 HOLES. ACIDIZE W/ 3000gal 15% NEFE HCL ACID, SWAB 0-BO, 20BLW IN 4 HRS. FRAC W/ 26000gal X-LINKED GELLED 2% KCL FW W/ 82000# 16/30 SAND. SITP-75#, REC 30BLW IN 2hrs, W/ HEAVY AMOUNT OF SAND. RU COIL TBG & CHC, SWAB 0-BO, 570 BLW IN 13HRS. RIH W/ CIBP & SET @ 3644'. PERF QUEEN W/ 2SPF @ 3453-56, 77-82, 90-3494, 3503-06, 14-43, 56-72, 74-82, 84-90, 94-3602, 15-3627' TOTAL 208 HOLES. ACIDIZE W/ 5000gal 15% NEFE HCL ACID. SWAB 231BLW IN 5hrs. POOH W/ TBG, NDBOP, NUWH, LEAVE 1jt 2-7/8" T3G, RDPD 7/13/94, SI WELL PENDING ENGR EVAL.

MIRU PU 3/21/95, RIH & TAG @ 3644', DRILL OUT CIBP @ 3644', CD TO 3838'. RIH W/ CR & SET @ 3638', EIR @ 2 BPM @ 0-PSI, M&P 100sx CL C CMT, COULDN'T CATCH CMT, SI WOC. RIH & TAG CR, DRILL OUT CR & TAG @ 3835'. RIH W/ CR & SET @ 3638', EIR @ 3 BPM @ 170#, M&P 100SX CL C W/ 2% CACL2 FOLLOWED BY 50sx CL C. SQZ TO 1400#, SI WOC. RIH & TAG @ 3638', POOH. RIH W/ 2-7/8" TBG & SET @ 3322'. RIH W/ 2-1/2"x 1-3/4"X 24' BHD PUMP ON 77-D RD STR. RDPD 3/28/95, INSTALL PU, POC & PUT WELL ON PRODUCTION.

NMOCD POTENTIAL TEST 3/30/95

22-HRS 13-O 29-W 1-G 39.0 API GRAV 77-GOR