## State of New Mexico

Submit 3 copies

(This space for State Use) APPROVED BY\_

Form C-103

\_DATE\_SEP 0 8 1994

DISTRICT III	o Appropriate District Office	E /, Minerals and N	aturai Kesouri	ces Department	R	levised 1-1-89
District   P. O. Box Drewer DD, Artesia, NM 88210   Santa Fe, New Mexico 87504-2088   6   Indicate Type of Lease No.		OIL CONSERV	ATION	DIVISION	WELL API NO.	
P.O. Box Drawer DD, Artsus, NM 88210  SARIG FE, New Mexico 87:004-2088  SINTET C.  SINTE	P.O. Box 2088				30-025-32551	
DISTRICT	Santa Fe New Meyico 8/504-2088				5. Indicate Type of Lease	
Scale   Sunday   Notices		210			STATE _	FEE 🔀
UNIDER THE FORM FOR PROPOSALS TO PRILLOR TO DEFEND RPLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Wall: OIL GAS WELL OTHER  2. Name of Operator  TEXACO EXPLORATION & PRODUCTION INC.  3. Address of Operator  JAMAT / LANGUE MATTIX  4. Well Location  Unit Letter P : 330 Feet From The SOUTH Line and 500 Feet From The LEA COUNTY  10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR.3315, KB-3327  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REWEDIAL WORK P LUG AND ABANDON CHANGE PLANS  TEMPORARILY ABANDON CHANGE PLANS  THE MORNALLY ABANDON CHANGE PLANS  OTHER: SPUD & SURFACE CASING  OTHER:	<del></del> _	10			6. State Oil / Gas Lease No.	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.  3. Address of Operator P.O. Box 3109, Midland Texas 79702  4. Well Location Unit Letter P: 330 Feet From The SOUTH Line and 500 Feet From The EAST Line Section 13 Township 24-S Range 36-E NMPM LEA COUNTY  10. Elevation (Show whether DF, RKG, RT,GR, etc.) GR-3315, KB-3327  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PREFORM REMEDIAL WORK PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDON COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT CASING TEXT AND CEMENT JOB SURFACE CASING OTHER: SPUD & SURFACE CASING SET GRAVE CA	SUNDRY NO (DO NOT USE THIS FORM FOR PR DIFFERENT RESI	OTICES AND REPORTS COPOSALS TO DRILL OR TO ERVOIR. USE "APPLICATION	DEEPEN OR I N FOR PERMI			ame
TEXACO EXPLORATION & PRODUCTION INC.  3. Address of Operator P.O. Box 3109, Midland Texas 79702 9. Pool Name or Widcat JALMAT / LANGLIE MATTIX.  4. Well Location Unit Letter P.: 330 Feet From The SOUTH Line and 500 Feet From The EAST Line Section 13 Township 24-S Range 36-E NMPM LEA COUNTY 10. Elevation (Show whether DF, RKS, RT,GR, etc.) GR.3315, KB.3327  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION LATERING CASING COMMENCE DRILLING OPERATION CASING TEXT AND CEMENT JOB OTHER: SPUD A SURFACE CASING OTHER: SPUD A SURFACE CASING OTHER SPUD A SURFACE CASING OTHER SPUD 12 1/4 INCH HOLE @ 8:30 PM 08-31-94. DRILLED TO 420. TD @ 12:00 AM 09-01-94.  2. RAN 10 JOINTS OF 8 18, 244, CF-50, STC CASING SET @ 420. RAN 5 CENTRALIZERS.  3. DOWELL CEMENTED WITH 250 SACKS CLASS CW/2% CACIC (14.8 PPG, 1.34 CF/s). PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 6. SACKS.  4. NU BOR 9 TESTED TO 12009. TESTED CASING TO 12009 FOR 30 MINUTES FROM 10:30 PM TO 11:00 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  5. GNATURE C BASHAM TITLE DRILLING OPErations Mgr.  1. DATE 18. 18. 18. 18. 18. 18. 18. 18. 18. 18.	i, lype or wen.					
4. Well Location  Unit Letter P : 330   Feet From The   SOUTH   Line and   500   Feet From The   EAST   Line   Section   13   Township   24-S   Range   36-E   NMPM   LEA COUNTY    10. Elevation (Show whether DF, RKG, RT, GR, etc.)   GR-3315, KB-3327    11.   Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data   NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:   REMEDIAL WORK   P.LUG AND ABANDON   REMEDIAL WORK   ALTRAING CASING   REMEDIAL WORK   ALTRAING CASING   REMEDIAL WORK   ALTRAING CASING   COMMENCE DRILLING OPERATION   P.LUG AND ABANDONMENT   CASING TEST AND CEMENT JOB   OTHER:   SPUD & SURFACE CASING    12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, including estimated date of star any proposed work) SEE RULE 1103.  1. CAPSTAR RIG #8 SPUD 12 1/4 INCH HOLE @ 8:30 PM 08-31-94. DRILLED TO 420'. TD @ 12:00 AM 09-01-94.  2. RAN 10 JOINTS OF 8 5/8, 248 (CF-50, STC CASING SET @ 420'. RAN 5 CENTRALIZERS.  3. DOWELL CHEMPTED WITH 205 SACKS CLASS CW / 2% CALIZ (14.8 PPG, 1.34 CFr.) PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 6: SACKS.  3. DOWEL CHEMPTED WITH 205 SACKS CLASS CW / 2% CALIZ (14.8 PPG, 1.34 CFr.) PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 6: SACKS.  4. NU BOP & TESTED TO 1200#, TESTED CASING TO 1200# FOR 30 MINUTES FROM 10:30 PM TO 11:00 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  5. FRANCO REPORT OF THE PROPERTY OF THE PROP		XPLORATION & PRODUCTIO	N INC.		8. Well No. 419	
Unit Letter P : 330 Feet From The SOUTH Line and 500 Feet From The EAST Line Section 13 Township 24-S Range 36-E NMPM LEA COUNTY  10. Elevation (Show whether DF, RKG, RT,GR, etc.) GR-3315, KB-3327  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  FERFORM REMEDIAL WORK PLUG AND ABANDON GEMENDIAL WORK AND ABANDON CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: SPUD & SURFACE CASING  OTHER: SPUD & SURFACE CASING  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of star any proposed work) SEE RULE 1103.  1. CAPSTAR RIG #8 SPUD 12 /14 INCH HOLE @ 8:30 PM 08-31-94. DRILLED TO 420'. TD @ 12:00 AM 09-01-94.  2. RAN 10 JOINTS OF 8 58, 24#, CF-50, STC CASING SET @ 420'. RAN 5 CENTRALIZERS.  3. DOWLEL CEMENTED WITH 250 SACKS CLASS C W/2% CACL2 (14.8 PPG, 1.34 CF/5). PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 65 SWOCT TIME 10.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  6. DRILLING 7 7/8 HOLE.  1 THERMON ME 15 AM TO 10:30 PM 09-01-94.  5 SIGNATURE C. T. DATE OF 15 AM TO 10:30 PM 09-01-94.  1 TILLE DATE OF 15 AM TO 10:30 PM 09-01-94.  1 TILLE DATE OF 15 AM TO 10:30 PM 09-01-94.  1 TILLE DATE OF 15 AM TO 10:30 PM 09-01-94.  1 TILLE DATE OF 15 AM TO 10:30 PM 09-01-94.  1 TILLE DATE OF 15 AM TO 10:30 PM 09-01-94.  1 TILLE DATE OF 15 AM TO 10:30 PM 09-01-94.  1 DATE 9/694	3. Address of Operator P.O. Box 31	09, Midland Texas 79702			1	TIX
Section 13 Township 24-S Range 36-E NMPM LEA COUNTY    10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3315, KB-3327     11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING COMMENCE DRILLING OPERATION ALTERING CASING COMMENCE DRILLING OPERATION OF COMMENCE DRILLING OPERATION OF COMMENT TEMPORARILY ABANDON OF CHANGE PLANS OTHER: SPUD A SURFACE CASING OTHER: SPUD A SURFACE CA	4. Well Location					
10. Elevation (Show whether DF, RK6, RT,GR, etc.) GR-3315, KB-3327  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:    SUBSEQUENT REPORT OF:   REMEDIAL WORK	Unit Letter P:	330 Feet From The	SOUTH_L	ine and <u>500</u>	Feet From The EAST Line	•
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:    SUBSEQUENT REPORT OF:   REMEDIAL WORK   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OFERATION   PLUG AND ABANDONMENT COMMENT   PLUG AND ABANDONMENT   PLUG A	Section 13	·	-			NTY
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK		10. Elevation (Show wheth	or DF, RKB, RT,	GR, etc.) GR-3315,	KB-3327'	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPERATION  PLUG AND ABANDONMENT COMMENCE DRILLING OPERATION  PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  THERE  PROPOSED OF THE SPUD & SURFACE CASING OTHER: SPUD & SURFAC	1. Check A	Appropriate Box to Indica	ate Nature o	of Notice, Report	t, or Other Data	
TEMPORABILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPERATION THER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of star any proposed work) SEE RULE 1103.  1. CASTAR RIG #8 SPUD 12 1/4 INCH HOLE @ 8:30 PM 08-31-94. DRILLED TO 420'. TD @ 12:00 AM 09-01-94.  2. RAN 10 JOINTS OF 8 5/8, 24ff, CF-50, STC CASING SET @ 420'. RAN 5 CENTRALIZERS.  3. DOWELL CEMENTED WITH 250 SACKS CLASS C W/2% CACL2 (14.8 PPG, 1.34 CF/S). PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 6 SACKS.  4. NU BOP & TESTED TO 1200#. TESTED CASING TO 1200# FOR 30 MINUTES FROM 10:30 PM TO 11:00 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  6. DRILLING 7 7/8 HOLE.  1. Nutries, sertily that the antomycron above is total and complete to the best of my browdedge and belate.  1. DITILITING OPERATION SMG.  DATE	NOTICE OF INTENTION	ON TO:		SU	JBSEQUENT REPORT OF	:
CASING TEST AND CEMENT JOB COTHER:  CASING TEST AND CEMENT JOB COTHER:  SPUD & SURFACE CASING  12. Describe Proposed or Completed Operations (Clearly state ell pertinent details, and give pertinent dates, including estimated date of star any proposed work) SEE RULE 1103.  1. CAPSTAR RIG #8 SPUD 12 1/4 INCH HOLE @ 8:30 PM 08-31-94. DRILLED TO 420. TD @ 12:00 AM 09-01-94.  2. RAN 10 JOINTS OF 8 5/8, 24#, CF-50, STC CASING SET @ 420'. RAN 5 CENTRALIZERS.  3. DOWELL CEMENTED WITH 250 SACKS CLASS C W/ 2% CACL2 (14.8 PPG, 1.34 CF/S). PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 6: SACKS.  4. NU BOP & TESTED TO 1200#, TESTED CASING TO 1200# FOR 30 MINUTES FROM 10:30 PM TO 11:00 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  6. DRILLING 7 7/8 HOLE.  Therefore Note: The first of the best of my boundadge and babe!  Drilling Operations Mgr.  DATE9/6/94  TILLEDRING NGR.  DATE9/6/94  Taleschare No688-46/98	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMI	EDIAL WORK	ALTERING CASING	
OTHER:	TEMPORARILY ABANDON	CHANGE PLANS	Сом	MENCE DRILLING OPE	ERATION 🔯 PLUG AND ABANDON	MENT
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of star any proposed work) SEE RULE 1103.  1. CAPSTAR RIG #8 SPUD 12 1/4 INCH HOLE @ 8:30 PM 08-31-94. DRILLED TO 420'. TD @ 12:00 AM 09-01-94.  2. RAN 10 JOINTS OF 8 5/8, 24#, CF-50, STC CASING SET @ 420'. RAN 5 CENTRALIZERS.  3. DOWELL CEMENTED WITH 250 SACKS CLASS C W/ 2% CACL2 (14.8 PPG, 1.34 CF/S). PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 6 SACKS.  4. NU BOP & TESTED TO 1200#. TESTED CASING TO 1200# FOR 30 MINUTES FROM 10:30 PM TO 11:00 PM 09-01-94.  5. WOC TIME 18:25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  6. DRILLING 7 7/8 HOLE.  1. DRILLING 7 7/8 HOLE.  1. DRILLING OPERATION OF THE BOOK	PULL OR ALTER CASING		CASI	NG TEST AND CEMEN	NT JOB 🔀	
any proposed work) SEE RULE 1103.  1. CAPSTAR RIG #8 SPUD 12 1/4 INCH HOLE @ 8:30 PM 08-31-94. DRILLED TO 420'. TD @ 12:00 AM 09-01-94.  2. RAN 10 JOINTS OF 8 5/8, 24#, CF-50, STC CASING SET @ 420'. RAN 5 CENTRALIZERS.  3. DOWELL CEMENTED WITH 250 SACKS CLASS C W/ 2% CACL2 (14.8 PPG, 1.34 CF/S). PLUG DOWN @ 4:15 AM 09-01-94. CIRCULATED 6 SACKS.  4. NU BOP 8 TESTED TO 1200#. TESTED CASING TO 1200# FOR 30 MINUTES FROM 10:30 PM TO 11:00 PM 09-01-94.  5. WOC TIME 18.25 HOURS FROM 4:15 AM TO 10:30 PM 09-01-94.  6. DRILLING 7 7/8 HOLE.  1. Thereby certify that the niferration above is tobe and complete to the base of my browdedge and baller.  SIGNATURE C. J. Basin T. Date 9/6/94  Title Drilling Operations Mgr.  DATE 9/6/94  Talesbore No. 688-46/88	OTHER:		🔲 отне	R:	SPUD & SURFACE CASING	🛛
SIGNATURE C. P. Basham   SOH TITLE Drilling Operations Mgr. DATE 9/6/94	any proposed work) SEE RULE 110  1. CAPSTAR RIG #8 SPUD 12 1/4 INCI  2. RAN 10 JOINTS OF 8 5/8, 24#, CF-5  3. DOWELL CEMENTED WITH 250 SA SACKS.  4. NU BOP & TESTED TO 1200#. TES  5. WOC TIME 18.25 HOURS FROM 4:1	D3. H HOLE @ 8:30 PM 08-31-94. 0, STC CASING SET @ 420'. ICKS CLASS C W/ 2% CACL2 TED CASING TO 1200# FOR	DRILLED TO RAN 5 CENTF 2 (14.8 PPG, 1	420'. TD @ 12:00 AM RALIZERS. 34 CF/S). PLUG DO	M 09-01-94. DWN <b>@</b> 4:15 AM 09-01-94. CIRCULA	_
TYPE OR PRINT NAME C. P. Basham	SIGNATURE C. P. Basha	1101	Drilling Op	perations Mgr.		

\_TITLE\_\_