

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Co.  
P.O. Box 1980  
Hobbs, NM 88241

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Santa Fe Energy Resources, Inc.

3. Address and Telephone No.

550 W. Texas, Suite 1330, Midland, TX 79701 915/687-3551

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

(D), 430' FNL and 330' FWL, Sec. 6, T-24S, R-32E

5. Lease Designation and Serial No.

NM-77064

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Mesa Verde "6"

Federal #10

9. API Well No.

30-025-

10. Field and Pool, or exploratory Area

Mesa Verde (Delaware)

Mesa Verde (Bone Spring)

11. County or Parish, State

Lea

NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1/4/98: Depth 8660'. TD 7-7/8" hole at 3:30 p.m. RU loggers.

1/5/98: Logging. Prep to plug.

1/6/98: Set Plug #1 at 8400' w/100' cmt. Set Plug #2 at 6400' w/100' cmt. Set Plug #3 from 4550'-4350' (200' plug) and tagged. Set Plug #4 at 2340' w/100' cmt. Set Plug #5 at 620' w/100' cement. Set surface plug from 50' to surface. Jet and clean pits. Released rig at 11:00 p.m. This well is plugged and abandoned.

14. I hereby certify that the foregoing is true and correct

Signed

*Erin McCullough*

Title Sr. Production Clerk

Date Jan. 27, 1998

(This space for Federal or State office use)

Approved by

*DR. SCOTT GARY GORLEY*

Title

PETROLEUM ENGINEER

Date FEB 19 1998

Conditions of approval, if any: