		N.M. Oil Cr. 3. Divi	sion
Form 3160-5 (June 1990)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	P.O. Box 1980 Hobbs, NM 88241	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
	SUNDRY NOTICES AND REPORTS ON WELL m for proposals to drill or to deepen or reentry t se "APPLICATION FOR PERMIT - " for such prop	NM - 77064 6. If Indian. Allottee or Tribe Name	
	SUBMIT IN TRIPLICATE		7. If Unit or CA. Agreement Designation
1. Type of Well Gas Well Gas Well			8. Well Name and No. Mesa Verde 6
2. Name of Operator	rgy Resources, Inc.	Federal #14	
3. Address and Telephone N		30 - 025 - 32753 10. Field and Pool, or exploratory Area	
4. Location of Well (Footag	650' FWL, Sec. 6, T-24S, R32E	Mesa Verde (Delaware)	
- <u></u>	APPROPRIATE BOX(S) TO INDICATE NATU		
Notice of Notice of Notice of Subsequ	UBMISSION of Intent ACCEPTED FOR RECORD Intent Report ACCEPTED FOR RECORD Plugging Dandonment Natice FED 0 6 1997 Casing I Altering Other Other	letion 5 Back Repair Casing	Change of Plans Change of Plans New Construction Won-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.)
13. Describe Proposed or Com give subsurface lo	pleted Operations (Clearly state all pertinent details, and give pertinent cations and measured and true vertical depths for all markers and zones	dates, including estimated date of star s pertinent to this work.)*	ting any proposed work. If well is directionally drilled,
	Kill well w/prod water. POOH w/ d POOH w/ tubing, LD BHA.	pump & rods.ND wel	lhead and NU BOP.
12/6/96: RIH w perfs w/ 2000 g	/ 4" csg guns and perforate the De als 7-1/2% NeFe acid and 59 ball se	laware 8364'-8402' ealers.	(39 holes). Break down
12/7/96: Made Monday.	14 swab runs, recovered 43.5 BW.	Shut down for weeke	nd and prep to frac on
12/10/96: RU D sand.	owell and frac down tbg w/ 47,900 g	gals gel containing	166,224 <b>#</b> 16/30 Ottawa
12/12/96: RIH 8570'-8585' plu	w/ RBP and set at 8500' and dump sa gged off. Begin swab testing.	and on top of RBP.	Bone Spring perforations
01/02/97: RIH	w/ rods and 2-1/2" x 1-1/2" pump.	Put well on produc	tion.
	foregoing is true and correct allocide Sr. Proc	luction Clerk	
(This space for Federal c Approved by Conditions of approval,	Title		Date
	11, makes it a crime for any person knowingly and willfully to make to matter within its jurisdiction.		ed States any false, fictitious or fraudulent statements
	* See Instruction on		csa l'erde BS do

ĸ	See	Instru	ction	on	Reverse	Sic
---	-----	--------	-------	----	---------	-----