

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32944
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	SIMS, R. R. 'A'
8. Well No.	6
9. Pool Name or Wildcat	TEAGUE SAN ANDRES, NORTH
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3324' GL, 3339' KB

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
PO BOX 3109, MIDLAND, TEXAS 79701

4. Well Location
Unit Letter M : 500 Feet From The SOUTH Line and 375 Feet From The WEST Line
Section 4 Township 23-S Range 37-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Permission to TA ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILL OPERATIONS ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject:

RR Sims A #6.

Texaco E & P 500 Loraine Midland, Texas 79702 respectfully requests permission to temporarily abandon the subject well.

Justification:

Texaco is currently evaluating future potential in this well.

Notify NMOCD 505-393-6161 prior to commencing work.

1-RU pulling unit pull and lay down rods and pump

2-NU BOP release tubing anchor TOH with tubing

3-TIH with casing scraper to 3990' TOH

4-RU WL and set a CIBP @ 3900'

5-Fill casing water, test to 550 psi for 30 min and chart.

File a C-103 subsequent report and request TA status



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Quintana TITLE Engineering Assistant DATE 11/5/01

TYPE OR PRINT NAME Mike Quintana Telephone No. 505-394-9307

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: