

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32944
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	SIMS, R. R. 'A'
8. Well No.	6
9. Pool Name or Wildcat	TEAGUE SAN ANDRES, NORTH

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u> </u> M <u> </u> : <u> </u> 500 <u> </u> Feet From The <u> </u> SOUTH <u> </u> Line and <u> </u> 375 <u> </u> Feet From The <u> </u> WEST <u> </u> Line Section <u> </u> 4 <u> </u> Township <u> </u> 23-S <u> </u> Range <u> </u> 37-E <u> </u> NMPM <u> </u> LEA <u> </u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3324' GL, 3339' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐ RECOMPLETE IN SAN ANDRES ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-12-01: MIRU. UNLOAD & RACK 147 JTS 2 7/8" WS. TIH TO 3950'. RUN GR/CCL 4100-3100. TIH W/PERF GUN. PERF IN SAN ANDRES FORMATION 3994-4006.
 3-13-01: TIH W/PKR, & SN ON WS. SET PKR @ 3904'. LOAD & TEST BACKSIDE TO 500#-OK. BREAKDOWN PERFS @ 3900#. ACIDIZE SAN ANDRES PERFS 3994-4006 W/3000 GALS 15% NEFE HCL. BALLOUT @ 4300#. SURGE OFF BALLS.
 3-14-01: RU SWAB. FL @ 200'. END FL @ 2800'. UNSET PKR & LOWER TO 4030'. TIH W/PIN COLLAR, SN, TBG & TAC. STOP @ 3808'.
 3-15-01: TIH W/2 3/8" TBG. TBG @ 4030'. SN @ 4001. TAC @ 3907'. NDBOP. NUWH. TIH W/PUMP, STRAINER NIPPLE, SNKR BARS ON RDS. LOAD & TEST TO 500#. PUMPING @ 3:00 PM. RIG DOWN.
 3-27-01: ON 24 HR OPT. PUMPING 8 BO, 66 BW, & 20 MCF.

SAN ANDRES PERFS: 3994-4006'

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. Denise Leake

TITLE Engineering Assistant

DATE 4/11/01

TYPE OR PRINT NAME

J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Orig. Signed by
Paul Kautz

DATE

DeSoto/Nichols 12-93 ver 1.0

2A SW Teague Glorieta 10000 Paddock