Form 3160-5 (August 1999)

## UNLIED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

		and the I
÷	1	FORM APPROVED
		OMB NO. 1004-0135
	i i	E '- N 1 40 400

Expires: November 30, 2000

5. Lease Serial No.

NM-68084

	SUNDRY	<b>NOTICES</b>	AND	<b>REPORTS</b>	ON	WELLS
--	--------	----------------	-----	----------------	----	-------

Do not use this form for proposals to drill or to re-enter an abandoned well Use Form 3160-3 (APD) for such proposals.

6.	If Indian,	Allottee or	Tribe	Name	

SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or	7. If Unit or CA/Agreement, Name and/or No.	
I. Type of Well  X Oil Well  Gas Well Other				8. Well Nam		
2. Name of Operator					Mesa Verde "7" Federal #7  9. API Well No.	
3a. Address 3b. Phone No. (include area code) 915/687-3551				30-025-33103  10. Field and Pool, or Exploratory Area Mesa Verde (Delaware) Mesa Verde (Bone Spring)  11. County or Parish, State		
				Lea	NM	
12. CHECK APPROPE	RIATE BOX(ES) TO I	INDICATE NATURE OF NO	TICE, REPOR	T, OR OTHER D	)ATA	
TYPE OF SUBMISSION		TYI	PE OF ACTION	l		
Notice of Intent	Acidize  Alter Casing	Deepen Fracture Treat	Production Reclamate	on (Start/Resume)	Water Shut-Off Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recompl		X Other	
Final Abandonment Notice	Change Plans  Convert to Inject	Plug and Abandon tion Plug Back	Tempora Water Di	rily Abandon sposal	Add Perfs	
3 Describe Proposed or Coommpleted Operation (clean If the proposal is to deepen directionally or recommendations).	arly state all pertinent det	tails, including estimated starting subsurface locations and measu	g date of any p	roposed work and tical depths of al	d approximate duration thereof.	

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3150-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

6/7/00 MIRU. POOH W/ pump and rods & tbg. GIH W/ 4" guns perf 4 JHPF @ 8257 to 8269'. GIH W/ RBP & packer, RBP set @ 8333' and packer set @ 8169'. Acidize perfs W/ 1500 bbl acid W/ 85 BS, release packer POOH. GIH W/ 2 7/8" tbg and packer set @ 8185'. MIRU BJ, start pumping pad, tbg loaded @ 1320#, pumped 1,2 &3# sand at an average of 1057# went to flush, RD BJ. GIH release packer POOH. GIH W/ 2 7/8" tbg set @ 8250', 2 1/2" x 1 1/4" x 20x22' RHBC-HVR pump and rods.

6/28/00 RDMO. Well returned to production in the Delaware and Bone Spring (covered by DHC-1188)

Test dated 7/1/00: 81 BO/D: 78 BW/D: 77 MCF

	z,			
		HEGORD		
	YORIG. SGD.) DAN	VID R. GLASS		
14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)  Bill Keathly	BLM	Title Regulato	ry Specialist	
Die Kauckly		Date 7-11-00		
THI	S SPACE FOR FEDERA	AL OR STATE OFFIC	CE USE	
Approved by		Title		Date
Conditions of approval, if any, are attached. Approval certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations thereo	o those rights in the subject l	t or Office		4

JUL 1 4 2000
DLEA
SWELL I'M