

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38. GEOLOGIC MARKERS

| FORMATION | TOP | BOTTOM | DESCRIPTION, CONTENTS, ETC. | NAME    | TOP         |                  |
|-----------|-----|--------|-----------------------------|---------|-------------|------------------|
|           |     |        |                             |         | MEAS. DEPTH | TRUE VERT. DEPTH |
|           |     |        |                             | Tansil  | 2703        |                  |
|           |     |        |                             | Yates   | 2864        |                  |
|           |     |        |                             | Rustler | 1096        |                  |
|           |     |        |                             | Salado  | 1460        |                  |

