

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut in pressures, and recoveries):				38. GEOLOGIC MARKERS			
FORMATION		DESCRIPTION, CONTENTS, ETC.		NAME	TOP		TRUE VERT. DEPTH
		BOTTOM			MEAS. DEPTH		
Permian	0	1170	Loose gravly unconsolidated, coarse, brownish gray	Rustler Salt Yates 7 Rivers	1158		
Rustler Anhydrite	1156	1431	Unconsolidated, whitish brown, salty		1431		
Salt	1431	1562	100% whitish salt		3043		
Anhydrite & Salt	1562	3043	Unconsolidated loosely packed, brownish gray		3440		
Yates	3043	3440	Sandy, brownish with show of oil in samples				
7 Rivers	3440						

