

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30 025 33717
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 20035
7. Lease Name or Unit Agreement Name State 19
8. Well No. 1
9. Pool name or Wildcat Wildcat - Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3541' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Cobra Oil & Gas Corporation	
3. Address of Operator P.O. Box 8206 Wichita Falls, Texas 76307-8206	
4. Well Location Unit Letter <u>G</u> : <u>1865</u> Feet From The <u>North</u> Line and <u>2165</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>24S</u> Range <u>33E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3541' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Halliburton BWB 7 5/8" permanent packer set @ 15,020' with 20' seal bore extension, 2 7/8" x 8' tbg sub, 2.188" "R" nipple, 2 7/8" x 8' tbg sub, 2.188" "R" nipple with WL entry guide. End of tbg @ 15,065'. Set plug in "R" nipple and dump sand to fill tbg sub and packer. Dump 20' cement on top of packer. Morrow zone to be temporarily abandoned to plug back and test Atoka.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rory Edwards TITLE Production Supervisor DATE 8/19/97

TYPE OR PRINT NAME Rory Edwards TELEPHONE NO. 940/716-5100

(This space for State Use)

ORIGINAL SIGNED BY WILLIAM'S
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: