

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cased intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION		TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	GEOLOGIC MARKERS		
					NAME	NEAR. DEPTH	TRUE VERT. DEPTH
gates		3270	3350	Drilling break NO intervals cased or drill stem tested	A		

Received
Hobbs
000
45578-1011