

NEW MEXICO E? RGY, MINERALS & NATURAL RESOURCES DEPARTMENT

August 10, 2000

Enron Oil & Gas Co ATT: Mike Francis P O Box 2267 Midland, TX 79702

RE: Property/Well Brinninstool 4 State #2-N, 4-24s-33e API #30-025-34571 Ochoa 15 Federal #2-F, 15-25s-33e API #30-025-34751

The enclosed forms are being returned to your company due to lack of sufficient or correct data required to properly process the forms. ALL DATA CIRCLED IN RED should be supplied or amended. Revised forms should be resubmitted ATTACHED TO THIS FORM to the address above with fifteen (15) days.

C-101 _____ Plugging bond is not in place for OGRID reflected on form. Contact Dorothy Phillips in OCD Santa Fe office: (505) 827-7137

- OGRID number does not exist for Operator as designated
- Proposed Bottom Hole location omitted
- Ground Level Elevation omitted

Proposed casing record incomplete or unacceptable

- BOP schematic not included or attached
- Other:

Form is not properly signed and dated Directional Drill: Project area, producing interval, kickoff point, surface location, and bottom hole location should be designated

Acreage to be dedicated to well should be outlined

Non-standard location. Approved order from Santa Fe not on file

Non-standard proration. Approved order from Santa Fe not on file

Other:

C-103

C-102

API number omitted

Proper well identification omitted

_____ Location data incorrect or insufficient

_____ Date(s) work performed omitted

_____ Tubing size and depth and/or packer setting omitted

____ Other:_

OVER

C-104X	Operator OGRID omitted
	Effective Date should be included in Item 3 Reason for Filing Code
	Bottom hole location omitted
	Transporter name/OGRID omitted or incorrect
	Location for new POD requested omitted
	Well Completion Data incomplete
	Well Test Data omitted
	Form is not properly signed and dated
	Operator Change: Signature and OGRID of previous operator required
	xx Other: Change of Operator is still requried for these two well. Please submit.
C-105	Lithology omitted
	Tubing record omitted
	Well location incomplete
	Casing record incomplete or omitted
	Production data incomplete
	Other:
Deviation Survey	Omitted
Directional Survey	Omitted. Directional Drill: required with correctly calculated Bottom Hole Location
Logs	Required on all wells: State, Federal and Private
Other:	
C-139	See Attached Form
C-140	See Attached Form

BY C-115 REPORTING.

•

•
