Submit 3 Copie ;
to Appropriate
District Office

í...

State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION		
2040 Pacheco St. DISTRICT II Santa Fe, NM 87505			WELL API NO. 30-025-35012
P.O. Drawer DL, Artesia, NM 88210			sIndicate Type of Lease
DISTRICT III 1000 Rio Brazo ; Rd., Aztec, NM 87410			STATE FEE
SUNDRY NOTIO	CES AND REPORTS ON WEL	LLS NOR PLUG BACK TO A	
DIFFERENT RESERV	OIR. USE "APPLICATION FOR PE 01) FOR SUCH PROPOSALS.)	ERMIT"	7Lease Name or Unit Agreement Name
Type of We I: OIL GAS			E. C. Hill "A"
WELL WELL U	OTHER)***	₀Well No.
Arch Petroleum Inc.			7
³ Address of Operator P. O. Box 10340, Midland, TX 7970	2-7340		∍Pool name or Wildcat Teague Simpson
Well Location	Feet From The South	4050	
Unit Letter :540 F	eet From The South	Line and 1850	Feet From The East Line
Section 27		Range 37	NMPM Lea County
	10Elevation (Show whether DF, 3265' GR	<i>RKB, RT, GR, etc.</i>)	
¹¹ Check App	propriate Box to Indicate Na	ature of Notice, Rep	port, or Other Data
NOTICE OF INT		,	EQUENT REPORT OF:
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	CHANGE PLANS	COMMENCE DRILLING OF	
PULL OR ALTER CASING		CASING TEST AND CEME	
OTHER:		OTHER: Spud, Set Su	rface, Intermediate & Production Casing
12Describe Propersed or Completed Operations (work) SEE RULE 1103.	Clearly state all pertinent details, and give	e pertinent dates, including esti	imated date of starting any proposed
			1/2" hole to 1072'. TD reached @ 0900 hrs 55 POZ "C" @ 12.8 followed by 200 sks CI "C"
+ 2% CaCl2 @ 14.8 ppg. Plug down 500# ok. NU BOP's & test to 1000# o	10/ 10/01/10/S 12/10/00 UTC 125 9	sks to surface. WOC 12	-1/2 hrs. Make cut-off. Weld on WH & test to
Intermediate & Production Csg - Drid	12-1/4" hole to 3017'. TD reache	ed @ 12.30 hrs 12/19/00	. Ran 79 jts 9-5/8" 40#, 43#, 43.5#, 47# &
by 175 sks CI "C" + 2% CaCl2 @ 14 8	nng Plug down @ 0400 brs 12	(20/00) Circ 126 also to	/ 110 sks 65:35 POZ "C" @ 12.4 ppg followed
7923'-7500' w/ 280 sks Cl "H" 9/10% (CD32 18# WOC Ready to kick	. BJ cmt'd w/ 592 sks H	9/10% CD 31, 17.5#. WOC. Set plug #2 @
BJ cmt'd 1st stage w/ 850 sks CI "H" +	-3% FL52 + $-3%$ CD32 + $-15%$ S	-10at shoe @ 9320". Flo SMS + 1% R3 @ 15 7 n	at collar @ 9274'. DV tools @ 6970' & 4980'.
.75% CD32 (2) 14.09 ppg. Plug down			i stage w/ 900 sks Cl "C" + .15% FL52 +
I hereby certify that the information above is true	e and complete to the best of my knowled	an and holiof	
SIGNATURE Cathy Ml		LE Operation Tech	DATE 02-16-01
TYPE OR PRINT NAME Cathy Tomberlin			TELEPHONE NO. 915-685-8100
(This space for Sta e Use)			
APPROVED BY		u dia sudi Desubai	in and a second s
CONDITIONS OF APPROVAL, IF ANY:	TIT	LE	
			M = N