

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35125
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	F.B. DAVIS
8. Well No.	10
9. Pool Name or Wildcat	NORTH TEAGUE TUBB
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3329'

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109, MIDLAND, TX 79702
4. Well Location	Unit Letter <u>C</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>8</u> Township <u>23-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3329'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPERATION ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐
	ALTERING CASING ☐
	PLUG AND ABANDONMENT ☐
	PRODUCTION CSG. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-24-01/5-07-01: DRLG CMT FR 1150-1190,1200-1274,1337,1494,1805,1930,2054,2180,2264,2400,2682,2807,3028,3062,3464,3733,3807,3963,4187,4400,4470,4898,4940. TIH TO 1200 & CUT 130 FT DRLG LINE. WASH TO 100' NO FILL. DRLG FR 4940-5033,5190,5339,5369,5836,5875,6156,6332,6394,6642,6704,6860,7080,7150. RAN PLATFORM EXPRESS LOG. LOGGERS TD IS 7150.PU 3 1/2" TBG. TAG BOTTOM @ 7150. CIRC TO SPOT SAND @ 6575'. SPOT 15000 LBS @ 6558'. DISPL W/40 BBLs. TIH TO 6558. SPOT 15000 LBS SAND. TAG SAND @ 6715'. PUMP 20,000 LBS SAND. TAG SAND @ 6520. LD 218 JTS DP & 10 JTS 3 1/2" TBG. RAN 5 1/2" CSG: 1 GUIDE SHOE, 1 SHOE JT, 1 FLOAT COLLAR. FLOAT COLLAR @ 6514. MARKER JT @ 6014. RAN SIX CENTRALIZERS. WASH CSG TO BTM FR 6450-6540. TAG SAND & CIRC OUT SAME. CMT W/1080 SX 35/65 POZ + ADDITIVES. TAIL IN W/300 SX 50/50 POZ. NDBOP. SET SLIPS ON CSG. NUWH. RELEASE RIG @ 9:00 AM 5-06-01.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 5/10/01

TYPE OR PRINT NAME J. Denise Leake Telephone No. 915-688-4752

(This space for State Use)

APPROVED PAUL F. KAUTZ TITLE PETROLEUM ENGINEER DATE APR 03 2002

CONDITIONS OF APPROVAL, IF ANY: _____