

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-35345

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator
Nearburg Producing Co.

Lease Name or Unit Agreement Name
Johnson Ranch 28 State Com.

Well No.
1

Address of Operator
3300 N. "A" St, Bldg 2, Ste 120, Midland, Tx, 79705

Pool name or Wildcat
Johnson Ranch Wolfcamp

Well Location

Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section 28 Township 24S Range 33E NMPM Lea County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3521 GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NPC has fished for 23 days with no success, spent in excess of \$370,000 on this fishing job. We would like to P & A the well as follows:
TOF - 2-7/8" tbg @ 12,190'. A well bore diagram is attached.

- Set 1st plug - 100' "H" cmt from 12,190' to 12,090'.
- Cut and retrieve 7" csg from free point 11,000'+-.
- 2nd plug "H" cmt from 50' in & 50' outside 7" to 10,950'.
- 3rd plug - 100' "H" cmt plug from 8,950' to 8,850'.
- 4th plug - 100' "H" cmt plug from 6,850' to 6,750'.
- 5th plug - 100' "H" cmt plug from 50' out & 50' in 9-5/8" csg shoe @ 5,202'.
- 6th plug - 100' "H" cmt plug from 3,650' to 3,550'. Base of Salt.
- 7th plug - 100' "H" cmt plug from 1,600' to 1,500'.
- 8th plug - 100' "H" cmt plug form 50' out & 50' in 13-3/8" csg shoe @ 809'.
- 9th plug - 10 sx cmt surface plug.
- Cut off wellhead and set dry hole marker.

Formation Tops - Atoka - 14,270', Wolfcamp - 12,250', 3rd Bone Spring - 11,900', T/Bone Spring - 9,140', Delaware - 5,200', Base of Salt - 3,600', TOS - 1,550'.

Verbal Approval - Paul Kautz - 1/30/02 @ 2PM NM time.

This Approval of Temporary
Abandonment Expires

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Drilling Superintendent

DATE 01-30-2002

TYPE OR PRINT NAME M. R. Willis

TELEPHONE NO. 915-686-8235

(This space for State Use)

APPROVED BY

TITLE

ORIGINAL SIGNED BY
PAUL E. KAUTZ
PETROLEUM ENGINEER

DATE

FEB 04 2002

CONDITIONS OF APPROVAL, IF ANY: