	bU (<i>submit in tri</i> Ley United St NEER EPARTMENT OF T GEOLOGICAL S	Approval e PLICATE) Land Office Land TATES Lease No. 05 THE INTERIOR Unit	агеан No. 43-R368.4. Expires 12-31-60. В СТИРИВ ОСТИРОВ ССТИ
NOTICE OF INTENTION TO DRILL. NOTICE OF INTENTION TO CHANGE PLANS. NOTICE OF INTENTION TO TEST WATER SHI NOTICE OF INTENTION TO RE-DRILL OR RE NOTICE OF INTENTION TO SHOOT OR ACID NOTICE OF INTENTION TO PULL OR ALTER NOTICE OF INTENTION TO ABANDON WELL.	JT-OFF SUBSI PAIR WELL SUBSI IZE SUBSI CASING SUPPI	EQUENT REPORT OF WATER SHUT-OFF EQUENT REPORT OF SHOOTING OR ACIDIZING EQUENT REPORT OF ALTERING CASING EQUENT REPORT OF RE-DRILLING OR REPAIR EQUENT REPORT OF ABANDONMENT LEMENTARY WELL HISTORY	
(INDICATE ABO Smily Flint Ray-USA Well No. is located SW, SW, Jet. 9 (4 Sec. and Sec. No.) Undersignated	D	REPORT, NOTICE, OR OTHER DATA) BCORDOF 1 The and 1980 ft. from $\begin{bmatrix} E \\ W \end{bmatrix}$ line of (Meridian)	,

The elevation of the derrick floor above sea level is 3154. ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

See attached program and plats.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Euryey before operations may be commenced.

Company Tennessee fas Transmission Company

Address Pox 307

Robbe, New Mexico

By Clertang A. V. ians

Title District roduction Superintendent

GPO 862040

TENNESSEE (LAS AND OIL COMPANY PROFNOSIS TO DEILL AND COMPLETE

Lease: Emily Flint Ray-USA

Well No.: 2

District: Hobbs

Field: Paduca Area

Location: 660' FSL & 1980' FEL, Sec. 9, T-25-S, H-32-S, Lea Co., New Mexico

Projected Horison: Delaware Sand

Estimated TD: 4800*

Estimated Elevation: 3407 G.L.

Drilling, Casing, and Cement:

- 1. Drill 12 1/4" hole to approximately 350'.
- 2. Cement 8 5/8" casing at approximately 350' w/sufficient volume to circulate.
- 3. Woo 24 hrs. Release pressure and install BOP after 12 hrs. Pressure test casing w/600 psi for 30 minutes after WOC 18 hrs.
- 4. Drill 7 7/8" hole to Delaware Sand core point at approximately 4650'. Exact coring depth to be determined by wellsite Exploitation Engineer.
- 5. Core from 4650' to 4800' w/7 13/16" diamond bit.
- 6. Set 52" casing at TD w/130 sacks of 50/50 Poznix "S" and regular with 2% gel (or equivalent).
- 7. MOC 18 hrs. Run temperature survey after WOC 3 hrs. Pressure can be released if float holds; otherwise, hold pressure on casing for 8 hours.
- 8. Run tubing and pressure test casing w/1500 psig for 30 minutes after WOC 18 hrs.
- 9. Displace water w/oil.
- 10. Release rotary rig.

Drilling Mud:

- 1. Drill w/fresh water native mud to TD. Mud properties will be adjusted to meet requirements for good samples, coring, and drill stem tests. Prior to coring or running a drill stem test, the mud should have the following properties: Viscosity 35-40, water loss 5 to loce or less in 30 minutes, filter cake 2/32" or less.
- 2. No oil will be added without consent of wellsite Exploitation Engineer.

Drill Stem Tests:

1. One drill stem test may be run in the Delaware Sand between 4600' and 4700'.

Drilling Time:

- 1. Record 1' drilling time from surface to TD using Geolograph.
- 2. Record 1' drilling time in addition to Geolograph while coring.

Drill Pipe Measurement:

- 1. Tally drill pipe on last two trips prior to reaching casing point.
- 2. Tally drill pipe in strain under company supervision at all casing points, coring points, drill stem test points, and at TD.

Samples

- 1. Catch one set of 10' drilling samples from 1300' to TD unless otherwise directed by wellsite Exploitation Engineer.
- 2. No time lag will be made in catching samples and 15 minute circulating samples will be caught for a period of one hour while circulating unless otherwise directed by the wellsite Exploitation Engineer.
- 3. Samples will be washed thoroughly, sacked, and labeled as directed by the wellsite Exploitation Engineer.
- 4. Two one-quart samples will be caught and labeled of any fluid recovered by drill stem tests.

Hole Deviation:

- 1. Run hole deviation every 100' on surface hole.
- 2. Run hole deviation survey on each trip for bit or every 500', whichever occurs sooner.
- 3. Maximum hole deviation from surface to TD shall be 4° .
- 4. If hole deviation changes more than 1 1/2 degrees in any 100' interval, a string reamer will be run to wipe out dog leg.
- 5. If hole deviation changes more than 2 degrees in any 100' interval, the hole shall be plugged back and straightened out.

SULLARY

- 1. Run OR/Sonic log from casing to TD and Laterolog from approximately LLOO' to TD.
- 2. Run temperature survey on 5 1/2" casing string after 500 8 hours.
- 3. Run GR correlation log through pay section after cementing 5 1/2" casing.

Completions

To be determined at total depth.

CARE LEVEL OF TO BY CONVERSIONCE

APPROVED:

C. . Mance

WEANG A. W. LANG

APPROVED:

A. W. Lang

CWN/nl

	WEL				ATION COMMISS		FORM C-128 Revised 5/1/57
	SEE	INSTRUCTIONS	FOR COMPLE	TING TH	IS FORM ON THE RE	VERSE SIDE	
				CTION			Vell No.
	messe Cas	& Trans.	1	Emi	ly Flint Ray	USA	2
o ~etter	Section Q	Tewash p 25	South	Pange 32	East	Lea Coun	tv
al Footage L	ocstion of Well:						
1980 und Level Ele	feet from the ev. Producing	East		660 	feet from the		line icated Acreage:
453.5	tester	tend		Cashed	imated		Acres
ubo bas ibe m mother. (65- li the answer wise? YES	ng5(to drill into) 329 (e) NMSA to question one i NO	and to produce fr 1935 Comp.) a ''ao,'' have the -if answet is ''y	סאד מאזע אסטי נש ב נמנפופאנום טל י פוס,'' דער פו טל	id to app ili she ow Coueciida	opriate the production	either for himself 3 by communitizat	"Sumer" means the perso or for himself and on agreement or other-
d the shawer	4	,			and Description		ECEIVED
							2 1960
							CORTAL SURVEY
		SECTIO	IN B		an alife yn gwyddiau yn affir yn anglynad of Rhyffrydd a'r ddan'r ann adylfradiau		TIPICA MEXICO
		Ī					(
	4			ł		2 1	fy that the information 1 above is true and com-
	ł					plete to the b	est of my knowledge and
		2				belief	
	5 8			1		Name	\wedge
						Clerk	Try hells Land
	Í.					Position	Production Sup
				ł		Company	
	2 1					Date	
	:			1		December	3., 3969
	:						
						1	
				1		•	
						I hereby certi	y that the well location
						shown on the	plat in SECTION B was
						shown on the piorted from t	plat in SECTION B was eld notes of actual
						shown on the piorted from t surveys made supervision, a	plat in SECTION B was eld notes of actual by me or under my ad that the same is true
						shown on the plorted from t surveys made supervision, a and correct to	plat in SECTION B was eld notes of actual by me or under my ad that the same is true
						shown on the piorted from t surveys made supervision, a	plat in SECTION B was eld notes of actual by me or under my ad that the same is true
						shown on the plorted from t surveys made supervision, a and correct to and belief.	plat in SECTION B was eld notes of actual by me or under my ad that the same is true the best of my knowledg
					1980'	shown on the plorted from t surveys made supervision, a and correct to	plat in SECTION B was eld notes of actual by me or under my ad that the same is true the best of my knowledg
			0		1980'	shown on the plorted from t surveys made supervision, a and correct to and belief. Date Surveyed 11- Registered P	plat in SECTION B was eld notes of actual by me or under my ad that the same is true the best of my knowleds the best of my knowleds the best of my knowleds
			-660**		1980'	shown on the plorted from t surveys made supervision, a and correct to and belief. Date Surveyed 11-	plat in SECTION B was eld notes of actual by me or under my ad that the same is true the best of my knowledg

Į