	Submit 3 Copies To Appropriate District Office	State o	f New M	[exico		Form C	-102
	District 1	Energy, Mineral			Form C-103 Revised March 25, 1999		
	1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		, , , , , ,
	District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-025-08170		
	District III 1220 South St. Francis Dr.				5. Indicate Type of Lease FEDERAL		
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505				STATE FEE		
	1220 S. St. Francis Dr., Santa Fe, NM				6. State Oil & Gas Lease No.		
	87505				Fell. Lease	LC-061936-	A
	SUNDRY NOTIO	CES AND REPORTS C	N WELL	S	7. Lease Name	or Unit Agreement Na	ime:
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFERN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
:	PROPOSALS.)				Cotton Draw Unit		
:	1. Type of Well: Oil Well Gas Well Other: TA'd Injector						
· · ·	Oil Well Gas Well Other: TA'd Injector 2. Name of Operator				7 77 1121		
•	SAHARA OPERATING COMPANY				7. Well No.		
	3. Address of Operator				9. Pool name or Wildcat		
•	P.O. BOX 4130, Midland, TX 79704				Paduca (Delaware)		
	4. Well Location		- · • - · · · · · · · · · · · · · · · ·		1 udden (D	ciawaic) .	
					•	•	- 1
	Unit Letter M :	660feet from the _	<u>SOUTH</u>	line and66	feet from	n the <u>West</u> li	ine
. •	Section 10	ren	0.7.0				- 1
1	Section 10	Township		Range 32-E	NMPM	County Le	ea
		10. Elevation (Show 3457' D	wneiner D	R, RKB, RT, GR, etc.)		
•	11 Check At	opropriate Box to Ir		latura of Niation I	0.11	D	
	NOTICE OF INT	FNTION TO:	idicate iv				
•		PLUG AND ABANDON	П		EQUENT RE		
		TEGG AND ABANDON	, 'n	REMEDIAL WORK	`	ALTERING CASING	; []
. :	TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND	П
	DILL OR ALTER CACING	A 41 (1 70-105) pro-	_			ABANDONMENT	ш
		MULTIPLE COMPLETION		CASING TEST AN	D		
		COMPLETION		CEMENT JOB			
	OTHER:	·		OTHER:		П	
	12. Describe proposed or completed of	operations. (Clearly sta	te all pert	inent details and give	nertinent dates i	ncluding estimated de	to of
	starting any proposed work). SEE	RULE 1103. For Mul	tiple Com	pletions: Attach well	bore diagram of n	ronosed completion of	r or
	recompilation.		•	•		- speare completion o	' 4
•	_					•	
•	Propose to repair casing & resur	ne TA status on we	ll. We d	esire to preserve t	his wellbore for	r possible future	
•	enhanced recovery.			•		1	
		• •					٠
	 Rig up, NU BOP. Ru 	n packer & bridge i	olug, Loc	cate casing leak.			٠
	2. Depending on depth	of casing leak, either	r saueez	e or pull and repl	ace casing	ENT 18 19 20 10	
	3. Pressure test casing, l	File C-103 requesting	ng TA st	atus	dee cusing.	allo Sign	
	8,		25 111 00	atas.		_	
•	•				•	를 대	
						₹ % } \$80	
		·		·	•) 를 (£0 -	
	I hereby certify that the information about	ye is true and complete	to the be	st of my knowledge a	nd belief		
	· X	MALL .		ar or my rare meage a	ind belief.	•	
	SIGNATURE SIGNATURE	Pylet:	TITLE	President		DATE7-9-02	
		/	*				_
	Type or print name Robert McA	lpińe			Teleph	one No.915-697-096	7
	(This space for State use)						
•	A DDDD OVER DA			ORIGINAL DITT		•	
	APPPROVED BY	7	TTLE	PALL F. L.		DATE JUL 1 6	2602
(Conditions of approval, if any:			PETROLEUM ELL	alliún		τούζ
		•		I ETHOLES			
. , T				•	•	• •	
p						•	
C							