Form 9-331a		Budget Bureau No. 42-R358.4. Approval expires 12-31-60.	
(Feb. 1951)	(SUBMIT IN TRIPLICATE)	Land Office Las Cruces	
	UNITED STATES DEPARTMENT OF THE INTERIOR	Lease No. LC - 062300 Unit	
<u>·</u>	GEOLOGICAL SURVEY		

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT	REPORT OF WATER S	SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS.		SUBSEQUENT	REPORT OF SHOOTIN	G OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SH	UT-OFF	SUBSEQUENT	REPORT OF ALTERIN	G CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR			
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT	REPORT OF ABANDO	NMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENT	ARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL					
Lease No. 186466 COTTON DPAW UNIT		TEXADO In	r. Notice, or other and the of		, 19 <u>61</u>
Well No. <u>46</u> is located	2130_ft. fro	$m_{-} \frac{\beta \gamma}{\beta}$ line and	<u>1 2130</u> ft. from	$   m \begin{pmatrix} E \\ W \end{pmatrix} $ line of set	<b>c.</b> <u>15</u>
N.1/li. SE/li, Sec. 15	25 - S	32 <b>-</b> E	NMPM		
(1/4 Sec. and Sec. No.)	(Twp.)	(Range)			
Undesignated	Lea		New	v Mexico	
(Field)	(Count	y or Subdivision)		(State or Territory)	

The elevation of the derrick floor above sea level is inknown ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

> TD - 1778: 7 5/8" OD Casing set at 332:

Ran 4768' or 4 1/2" OD Casing, 9.50 lb., J-55, 8 - R, and cemented at 4778' with 200 sx Incor. Plug at 310'. Job complete 7:55 P. M. April 22, 1961.

Tested 4 1/2" OD Casing for 30 minutes with 1500 PSI. From 8:00 to 8:30 P.M. April 23, 1961. Tested O.K. Drilled cement plug and re-tested for 30 minutes with 1500 PSI from 10:30 to 11:00 P.M. April 23, 1961. Tested O.K. Job complete 11:00 P.M. April 23, 1961.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	TEVACO Inc.			
Address	P. O. Box 352			
····	Midland, Texas	By <u>7 m. 2007</u>		
	J. <del>G.Blevins,</del> Jr.	Title As <del>sistu</del> nt District Superintendent		
	F. M. Loop	GPO 862040		