

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002508193
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-5009
7. Lease Name or Unit Agreement Name COTTON DRAW UNIT
8. Well No. 13
9. Pool name or Wildcat PADUCA DELEWARE
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3438' DF

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION	
2. Name of Operator Texaco Exploration and Production Inc.	
3. Address of Operator P. O. Box 730 Hobbs, NM 88240	
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>16</u> Township <u>22S-25</u> Range <u>32E</u> NMPM LEA	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-30-92 Plug & Abandon Well - Report on back

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L.W. Johnson TITLE ENGR ASST DATE 10-06-92
TYPE OR PRINT NAME L.W. JOHNSON TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Lyle F. Turnackliff TITLE OIL & GAS INSPECTOR DATE DEC 23 '92
CONDITIONS OF APPROVAL, IF ANY:

C. W. B.

E

DASS OIL WELL SERVICING

INCORPORATED

TEXACO EXPLORATION & PRODUCTION
COTTON DRAW UNIT - #13

10/28/92 - MOVE-IN, RIG UP, INSTALL B.O.P., PULL AND LAY DOWN
129 JOINTS OF 2 3/8" P.U. TUBING, RUN BIT AND
DRILL COLLARS AND 2 3/8" TUBING, TAG CAST IRON
BRIDGE PLUG AT 4102', SHUT DOWN.

10/29/92 - DRILL OUT CAST IRON BRIDGE PLUG, CLEAN OUT TO
4588', PULL TUBING AND BIT, RUN A NEW CAST IRON
BRIDGE PLUG IN HOLE TO 4575', SET CAST IRON BRIDGE
PLUG, CIRCULATE 10# OF SALT GEL MUD, SPOT 5 SACKS
OF CEMENT FROM 4575' - 4500', PULL TUBING OUT,
PERFORATE WELL AT 1140', 2 SHOTS, SHUT DOWN.

10/30/92 - RUN CEMENT RETAINER, SET AT 1090', PUMP 50 SACKS
OF CEMENT UNDER RETAINER AT 1000#, STING OUT OF
RETAINER, SPOT 5 SACKS OF CEMENT FROM 1090' - 1015',
PULL TUBING TO 400', TRY TO CIRCULATE WELL THROUGH
HOLE IN CASING, WOULD NOT CIRCULATE, PUMP 30 SACKS
OF CEMENT FROM 400' TO SURFACE IN 4 1/2" CASING,
PULL TUBING, CUT OFF WELLHEAD, FILL CASING WITH
CEMENT, INSTALL MARKER, RIG DOWN, MOVE OFF.

505-392-8591 • P.O. BOX 2545 • HOBBS, NEW MEXICO 88241

HOBBS, NEW MEXICO (505) 392-8591
ANDREWS, TEXAS (815) 823-4420
EUNING, NEW MEXICO (505) 392-8597
MIDLAND, TEXAS (815) 883-8595

RECEIVED

NOV 05 1992

OFFICE HOBBS