

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SEP 23 8 53 AM '66

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
State - E-5009

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Cotton Draw Unit
3. Address of Operator	8. Farm or Lease Name
TEXACO Inc.	Cotton Draw Unit
4. Location of Well	9. Well No.
UNIT LETTER <u>7L</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM	3
THE <u>North</u> LINE, SECTION <u>16</u> TOWNSHIP <u>25-S</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat
	Paduca Delaware
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3435' (GR)	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

We propose to do the following work on subject well:

1. Pull rods & tubing, and clean out to the total Depth of 4778'.
2. Frac well with 2000 gallons refined oil & 2000 pounds of sand.
3. Swab well, recover load oil, Test, place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dan Gillett TITLE Assistant District Superintendent DATE September 23, 1966

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: