

# HC - BS OFFICE COPY

Form 9-281a  
(Feb. 1961)

Budget Bureau No. 43-E288.4  
Approval expires 12-31-60.

(SUBMIT IN TRIPLICATE)

Field Office LC-061873-A

		X
<b>APPROVED</b>		
JUN 2 1959		
T. E. GODFREY ACTING DISTRICT ENGINEER		

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

186150  
**RECEIVED**  
SEP 30 1958  
U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Jack B. Shaw Federal

Hobbs, New Mexico September 4, 1958

Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 18  
NW  $\frac{1}{4}$  NE  $\frac{1}{4}$  Sec. 18 T-25-S R-32-E NMPL  
( $\frac{1}{4}$  Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3418 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD - 8511'

Well plugged and abandoned as follows:

1. Left 19 joints or 737' of 13 3/8" OD 48# casing and 132 joints or 4310' of 9 5/8" OD 36# casing in hole.
2. Spotted 45 sacks of cement (1st plug) from 8350' - 8250'. Spotted 60 sacks of cement (2nd plug) from 7000' - 6900'. Spotted 50 sacks of cement (3rd plug) from 5750' - 5650'. Spotted 50 sacks of cement (4th plug) 4380' - 4280'. 5th plug, 10 sacks in surface.
3. Clean and level location and install marker. Plugged and abandoned on the 8-26-58.

62-59 Sec inspected OK. JES

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address P. O. Box 458,

Hobbs, New Mexico

By [Signature]

Title Field Foreman

GPO 9 18 507

30-025-08200