DIL CONS. COMMISSION r.J. BOX 1980 HOBBS, NEW MEXICO 88240

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No. BUREAU OF LAND MANAGEMENT LC-061869 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Cotton Draw Unit 1. Type of Well B. Well Name and No. X Well Cotton Draw Unit #42 2. Name of Operator 9. API Well No. Texaco E&P, Inc. 30-02508201 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area P. O. Box 730-Hobbs, NM 88240 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Paduca Delaware 11. County or Parish, State Sec 20 R-35E Unit Letter I Lea County, New Mexico 32 1650 FSL & 330 FFL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of Intent **New Construction** Recompletion Non-Routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Disnose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Notify BLM of intent to move in. 8-14-95 Tag CIBP @ 4500'. 8-15-95 Cap CIBP w/30 SX cmt, Cal TOC 4066'. 8-15-95 Perf. 1195', sqz 85 sx cmt below pkr. Shut in @ 600 psi. WOC 4 hours. Tag TOC @ 1038. 8-16-95 Perf 450', circ. 130 sx cmt to surf. on $4\frac{1}{2}$ " x 8-5/8" ann. Tag TOC 60'. 8-16-95 8-16-95 8-17-95 5 sx cmt 60' - 0' 8-17-95 Rig down, ND BOP, cut wellhead off, cap and install dry hole marker. 8-17-95 Approved as to piugging of the well bore Liability under bood is retained until surface restoration is completed. 14. I hereby certify that the foregoing is true and correct J. Calder P&A Supervisor Tiele

(This space for Forth

Conditions of approval, if any:

