

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)DE-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-061369

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Cotton Draw Unit

8. FARM OR LEASE NAME

9. WELL NO.

28

10. FIELD AND POOL, OR WILDCAT

Paduca Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21, T-25-S, R-32-E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME	
TEXACO Inc.			
3. ADDRESS OF OPERATOR		9. WELL NO.	
P.O. Box 728, Hobbs, New Mexico 88240		28	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT	
1980' FSL & 1980' FEL of Sec. 21, T-21-S, R-32-E, Unit letter J.		Paduca Delaware	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
Regular	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	
	3410' DF	Lea	
		13. STATE	
		N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pulled rods and pump, tagged bottom @ 4650, pulled tubing Ran sand pump and cleaned out from 4650-4720.
2. Ran 2-7/8" tubing w/packer set @ 4580'. Loaded annulus w/20 Bbls. fresh water. Fraced perforations 4630-62' down 2-7/8" tubing w/600 gals. 15% NEA & 9000 gals. Emulsifrac w/375# Adomite & 13,500# 10/20 sand 1-1/2 to 3# gal. Used 250# Divert-2 & 250# rock salt for block between 3 equal stages. Pulled tubing and packer.
3. Checked TD w/sand line @ 4720'. Ran 2-3/8" tubing, could not get below 4606, pulled out of hole. Cleaned out 4606-10'. Tagged bottom @ 4720' and cleaned out to 4733'.
4. Ran 2-3/8" tubing, rods and pump, returned to production.
5. On 24 hour test, 4-14-74, pumped 115 BNO, 33 BSW, gravity 39.0, GOR 1260.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE 4-16-74

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

APR 16 1974

U.S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.