

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M.I. OIL CONS. COMMISSION  
P.O. BOX 1980  
HOBBS, NEW MEXICO 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Well  Gas Well  Other

2. Name of Operator

Texaco E&P, Inc.

3. Address and Telephone No.

P. O. Box 3109 - Midland, TX 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit 0 990' FSL; 2310' FEL Sec. 21 T-25S R-32E

5. Lease Designation and Serial No.

LC-062300 LC-061869

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Unit 0

8. Well Name and No.

Cotton Draw/Unit #44

9. API Well No.

30-025-08214

10. Field and Pool, or Exploratory Area

Paduca Delaware

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- Notice of Intent  
 Subsequent Report  
 Final Abandonment Notice

TYPE OF ACTION

- Abandonment  
 Recompletion  
 Plugging Back  
 Casing Repair  
 Altering Casing  
 Other
- Change of Plans  
 New Construction  
 Non-Routine Fracturing  
 Water Shut-Off  
 Conversion to Injection  
 Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- Notify BLM prior to plugging and abandonment of well.
- TIH w/tubing & tag cement @ 4510'. Circulate well w/25# per bbl. Salt gel mud.
- POOH to 4403'. Spot 25 sx cement plug f/4403'-4303' (Btm of salt 4353').
- Perf. & sqz. @ 1200' w/85 sx cement w/packer @ 1050'. WOC & tag. (Top of salt 1150').
- Spot 25 sx cmt plug f/804'-704' (Rustler 754').
- Perf. 4 1/2" casing @ 450' & circ cement to surface behind 4 1/2" casing. Leave inside of 4 1/2" casing full of cement from 450' to surface. approx. 165 sx cement.
- Nipple down BOP & cut off wellhead; cap well & install dry hole marker. Clean up location & move off.

RECEIVED  
 MAY 18 10 54 AM '95  
 OIL AND GAS  
 DIVISION

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Operations Engineer Date 5/16/95

(This space for Federal or State office use)  
 Approved by Orig. Signed by Shannon J. Shaw Title FEDERAL ENGINEER Date 6/30/95

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NOT POSTED  
MP

**RECEIVED**

JUL 06 1995

UCD HOBBS  
OFFICE