

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002508235
5. Indicate Type of Lease	<i>Led</i> STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LC-062300

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER *Injection*

2. Name of Operator
Texaco Inc.

3. Address of Operator
P.O. Box 730, Hobbs, NM 88240

4. Well Location

Unit Letter *A* : *330* Feet From The *North* Line and *330* Feet From The *East* Line

Section *29* Township *25S* Range *32E* NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3376' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU PU.
- 2) RU WL trk. Run free pt survey. Cut 4-1/2" csg above free pt w/jet cutter and pull csg. (TOC calc. @ 4150').
- 3) GIH w/WS to top of 4-1/2" csg stub. Ld hle w/salt gel mud consisting of a 10# brine containing 25# gel/bbl.
- 4) Spt 30 sx cmt across 4-1/2" csg stub. (Cmt vol. calc. to cover 50' inside 4-1/2" csg and 50' inside 6-3/4" OH). SION.
- 5) Tag cement plug.
- 6) Spt 50 sx cmt from 1000-900' (top of salt section).
- 7) Spt 40 sx cmt across 7-5/8" csg shoe. (Cmt volume calc. to cover 50' inside 6-3/4" OH & 50' inside 7-5/8" csg).
- 8) Spt 10' plug at surf.
- 9) Cut off WH. Install marker.
- 10) RD PU. Cln locn.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. A. Head* TITLE Area Manager DATE 11/13/89
TYPE OR PRINT NAME J. A. Head TELEPHONE NO. (505) 393-7191

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE NOV 15 1989

CONDITIONS OF APPROVAL, IF ANY:

R. R.