

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME <b>NMFLU</b>	
2. NAME OF OPERATOR <b>CONTINENTAL OIL COMPANY</b>		8. FARM OR LEASE NAME <b>WELLS B-1</b>	
3. ADDRESS OF OPERATOR <b>Box 460, Hobbs, N.M. 88240</b>		9. WELL NO. <b>1</b>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <b>660' FNL &amp; 660' FEL OF SEC. 1</b>		10. FIELD AND POOL, OR WILDCAT <b>JALMAT 4425</b> <b>7-Rivers</b>	
14. PERMIT NO.		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA <b>Sec. 1, T. 25S, R. 36E</b>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>3252' DF</b>		12. COUNTY OR PARISH <b>LEA</b>	
		13. STATE <b>N.M.</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☒ **SET CIBP & PERF**

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**SET CIBP AT 3120' W/2 3XCMT. SPOTTED  
250 GALS. ACID AT 3028'. PERF 3022-28' W/2 JSPP.  
RAN TBG. SWBD WELL DOWN. RAN PRODUCING  
EQUIPMENT. TESTED; PUMPED 11 Bp, 160 B/W &  
310 MCF/G ON 3-25-76.**

18. I hereby certify that the foregoing is true and correct

SIGNED

**Wm. A. Duthie**

TITLE

**ADMIN. SUPV.**

DATE

**5-15-76**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

**ACCEPTED FOR RECORD**

**JUN 23 1976**

**J. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO**

\*See Instructions on Reverse Side

**USGS (5), NMFLU (4) FILE**