Application for Authorization to Inject Maralo Inc. Jalmat Yates Unit #2 Page 2

- VIII. continued
  - 2. The Santa Rosa fresh water zone overlies the proposed injection formations at a depth of approximately 520'. There are no fresh water zones underlying the formation.
- IX. The proposed disposal interval may be acidized with 15% HCL acid and a small frac treatment.
- X. Well Logs are filed at the Hobbs OCD office.
- XI. The location of fresh water wells and windmills existing within a one mile radius of the subject location are noted on the map. Water Analysis is Exhibit "F".
- XII. Maralo, Inc. has examined geologic and engineering data and has found that there is no evidence of faulting or other hydrologic communication between potential fresh water aquifers and the desired injection zone.
- XIII. Proof of Notice

A copy of Form C-108 with the Statement of Compliance and associated exhibits has been sent by certified mail as follows:

Α.	Surface	Owner:	Clay Osborn
			P. O. Box 1285
			Jal, NM 88252

B. Offset Operators: Prime Operating Company 731 Wadley Avenue, Bldg. L North Park Executive Center Suite L-220 Midland, TX 79705

> Tenison Oil Company 8140 Walnut Lane, Suite 601 Dallas, TX 75231

MNA Enterprises Ltd. Company Box 755 Hobbs, NM 88241