

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.
02-J-12-25S-36E

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Maralo Jalmat Yates Unit

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Maralo, Inc.

8. Well No.

2

3. Address of Operator

P. O. Box 832, Midland, Texas 79702 0832

9. Pool name or Wildcat

Jalmat Tansill Yates Seven Rivers

4. Well Location

Unit Letter J : 2310 Feet From The South Line and 1650 Feet From The East Line

Section 12 Township 25-S Range 36-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-2-91 OPERATION P&A - RU Cobra Well Service. Installed BOP. RU Black Warrior WL. RIH w/gauge ring & junk basket to 2850'. POH. RIH w/5 1/2" CIBP set @ 2796' GL. Capped w/35' cmt. POH. RD WL. RIH to 2704. RU Halliburton. Pumped 100 bbls 10# brine mixed w/25#/bbl salt get. RD Halliburton. POH w/tbg.

12-3-91 Removed BOP. RU csg. pullers. Removed 5 1/2" csg packing on top of wellhead. Free-point @ 740' FS.

12-4-91 RU csg. crew. POH & LD 23 jts 5 1/2" pipe. RD csg. crew. RIH w/87 jts 2 3/8" tbg. POH w/tbg. LD 62 jts. RU Halliburton. Spot cmt plug w/100 sx Class C Neat, 50' inside 5 1/2" csg up to shoe on 10 3/4" csg & 50' inside. RD Halliburton. POH w/25 jts. Wait 4 hrs fro cmt to set. RIH w/tbg. Tagged plug 540' FS. POH w/tbg & Ld. Left 2 jts in hole. RU Halliburton Pumped 20 sx until cmt circ'd to surface. POH w/tbg. LD 2 jts. REMOVED 10 3/4" wellhead. Weld plate & dry hole marker over 10 3/4" csg collar. Well now P & A'd. Cleaned up location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Brenda Coffman

TITLE Agent

DATE 5-15-92

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Charlie Perrin

TITLE

DATE

OIL & GAS INSPECTOR

SEP 16 1993

CONDITIONS OF APPROVAL, IF ANY:

JWC

5