

DEPARTMENT OF THE STATE GEOLOGIST

WELL RECORD

Mail to State Geologist, Santa Fe, New Mexico, not more than ten days after completion of well. Indicate questionable data by fol-

ARE LOCATE	EA 640 ACRES WELL CORREC	TLY		atter	lowing it		ndicate qu . Submit			
Company	<u> </u>) Jaa	& Fuel	(Me)	Addre	ss	rtles	villo	Okla.	**************************************
									-	
										5
										County.
	land the oil a									
		_			_			•	29	
										eville, tala
										₁₉ 34
										le, Jemas
Elevation	above sea lev	vel at top	of casing	J144		feet.				
The infor	mation given	is to be l	kept confiden	tial until				19		
	E 60 m C				ANDS OR					
No. 1, fro	om 5275		to	277	No. 4,	from			to	
No. 3, fro	om		to		No. 6,	from			to	
			IM	IPORTAN	IT WATE	R SANI	ns.			
No 1 fro	om								to	
									. to	
_,, _,						***************************************				
	(2)			CAS	SING REC	ORD	<u> </u>			
SIZE	WEIGHT PER FOOT	THREA PER IN	DS MAKE	AMOUNT	KIND OF SHOE		D PULLED ROM	PE FROM	RFORATED	PURPOSE
125	50	8		60		110	one			
95/8 7	40 24	8 10		1426 3272			one			
		, `								
										1
=		ī			D CEMEN	TING F	RECORI)		
SIZE	WHERE SE	r No	D. SACKS OF C	EMENT	METHODS		MUD GR	AVITY	AMOUNT OF	MUD USED
12} 9 5/8	7426		50 500	-	Hallto	urton_				
7	5272		400		***					
_				Leng	-			_	et	
				SHOO	TING RE	CORD				
SIZE	SHELL	USED	EXPLOSIV	E USED	QUANTIT'Y	DATE	DEP	гн ѕнот	DEPTH CL	EANED OUT
								7.98 7.884 9.88		· · · · · · · · · · · · · · · · · · ·
		,				. !		· · · · · · · · · · · · · · · · · · ·		
				T	OOLS USI	ED				
Rotary to	ools were used	from	0	feet to	277 fe	et, and fi	rom		feet to	feet
Cable too	ols were used	from		feet to	fe	et, and fi	rom	1	feet to	feet
				DD	ODUCTIO	N N I				
Dut t	o producing	10-1	1	, ₁₉ 2)I N				
	-					fluid of	which I	100	% was oil;	0 "
									% was on;	
									of gas	
•	pressure, lbs.	•				is gasonii	ie per 1,00	o cu. 11. (oi gas	
				F	EMPLOYE	S				
نه و قد	eimen.			D	riller	J.3	ംധതമ			, Driller
J.	. dunter			, D	riller					, Driller
				,						
			-		RECORD (_		
	eby swear or it so far as ca					s a compl	iete amd co	prect reco	ord of the well	and all work
	cribed and sw					***************************************	D D	120	edio	·····
	~ /						, - ,	ndont	Product	
	,		^	uns	Repre		ngire	Jag .	Auel Co	-
My com	mission exp ire	es.Js	ly Fin	1938) Labor	E is howed	Çomp	oany or Operator
		//								

Decomposition Decompositio	***************************************			FORMATION RECORD
16 310 295 Sand & Fravol 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	FROM	TO	THICKNESS IN FEET	FORMATION
2782 2678 486 Anhydrite and An	15 510 415 506 1096 1145 1160 1228 1347 1410 1446 1446 1725 1765	310 415 506 1096 1145 1160 1228 1347 1410 1426 1725 1765 2047	295 105 91 590 49 15 68 119 63 16 20 279 40 282	Red Rock Sand & Gravel Sand Red Bad Anhydrite Red Rock Anhydrite Anhydrite Anhydrite- Broken Anhydrite- Rard Anhydrite- Broken
2946 2995 58 i.i.me and i.i.me an	2142 2192 2678 2756 2793 2826	2192 2678 2756 2793 2826 2914	57 486 78 43 33 88	Anhydrite & Salt Anhydrite A Salt Broken Anhydrite & Lime Lime Sandy
	29 40 29 9 5 3072	29 9 8 5 072 5 09 8	55 79 21	Lime-Sandy Lime Broken Lime & Sand