

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

DEC 17 11 22 AM '91

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-032581B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sholes B-13 No. 2

9. API Well No.

30-025-09762

10. Field and Pool, or Exploratory Area

Galmat Gates 7 Rvs Jansil

11. County or Parish, State

Lea, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Conoco Inc.

3. Address and Telephone No.

10 Dosta Drive, Ste 100 W, Midland, TX 79705 (915) 686-5494

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FNL * 660 FWL, Sect. 13, T25S, R36E Unit B

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Pull + lay rods down, 116 3/4". SD. Install BOP, pull fully tbg, run bit + scraper to 2800. Pull out, run cast iron bridge plug to 2700, set cast iron bridge plug, circ well w/mud, spot 20 sxs cmt from 1280, pull tbg, wait 4 hours, run tbg back, tag cmt at 1105, pull tbg, perf well at 1000', try to pump into well, bit could not press tst to 1000' #s, run tbg back to 1050, spot 20 sxs cmt, pull tbg. SP. Run tbg in hole, tag cmt at 920, pull tbg out, perf well at 250. Circ well, pump 100 sxs cmt down 7" csg to 250 up 9 5/8" csg to surf, cut off well head, pull csg w/cmt, set P&A marker on 9-24-91

14. I hereby certify that the foregoing is true and correct

Signed Christine L. Neff

Title Admin. Assistant

Date 12-12-91

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date 12-20-91

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side