

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. LC-032581B
2. NAME OF OPERATOR Conoco Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FWL - Unit Letter D	8. FARM OR LEASE NAME Sholes B-13
14. PERMIT NO. 30-025-09762	9. WELL NO. No. 2
15. ELEVATIONS (Show whether DF, RT, CR, etc.)	10. FIELD AND POOL, OR WILDCAT MIRU / Palmat Yates TR
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 13-25S-36E
	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☒
(Other) <u>Test Additional Pay</u>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and completion of this work.)

1. MIRU. Tally out w/ 2 1/8" Hg, SN, OEMA & 7" model "C" pku.
2. Drill thru CIBP & cement at 3060' & 3099'.
3. Set RBP at 3115' & pku at 3000'. Pressure test to 1500 psi. Rel pku & circulate hole clean w/ 9.0 ppg brine. Place EOT at 3113'. Spot 4 bbls 15% HCL-NE-FE acid inhibited for 48 hrs at 90°F from 3115'-3006'. Displace w/ 17.4 bbls 9.0 ppg brine & POOH.
4. Perforate 3020'-3110' w/ 2 jspr for total of 48 shots. POOH.
5. Set pku at 3000'.
6. Acidize w/ 2500 gals 15% HCL-NE-FE acid inhibited for 24 hrs plus 60 ballsealers. Flush w/ 22.5 bbls 9.0 ppg brine. Shut-in for 1 hr.
7. Seal well

If you have any questions please contact Rick Toothman at 393-4141.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] D. F. FENNEY

TITLE Administrative Supervisor

DATE March 1, 1988

(This space for Federal or State office use)

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

DATE 3-15-88

*See instructions on Reverse Side

Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad(6) ARCO(2) Amoco(2) Chevron (1) File