

Form 101 (10/53)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
verse side)

IF
IF

30-025-09788

EXP. DATE 11/1/85
EXP. DATE 11/1/85

5. LEASE DESIGNATION AND SERIAL NO.

0563093 NM-021796

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

WISER FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Jalmat T-Y-SR

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC24T-25-S R-36-E

12. COUNTY OR PARISH

LEA

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

JOHN S. GOODRICH

3. ADDRESS OF OPERATOR

P.O. BOX 69090 ODESSA TX 79769-9090

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1 MILE WEST OF JAL NEW MEXICO

14. PERMIT NO.

NM 021796

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. 2-6-90 SET 5-1/2 CIBP @ 3250' & CAP W/5 SX CMT. Circ. Hole W/9.5 Mud
2. 2-8-90 SPOT 50 SX PLUG @ 2066' (5-1/2 CSG STUB)
3. 2-8-90 TAG PLUG @ 1943'
4. 2-8-90 SPOT 65 SX PLUG @ 1300' (SALT)
5. 2-9-90 TAG @ 1240'
6. 2-9-90 SPOT 50 SX PLUG @ 1240'
7. 2-9-90 TAG @ 1099'
8. 2-9-90 SPOT 70 SX PLUG @ 591' (50 BELOW 8-5/8" SHOE)
9. 2-12-90 TAG @ 480'
10. 2-12-90 SPOT 65 SX PLUG FROM 237' TO SURF.
11. 2-12-90 CUT OFF WELLHEAD & INSTALL DRY HOLE MARKER.

ILLEGIBLE

18. I hereby certify that the foregoing is true and correct

SIGNED

Mel P. Heath

TITLE SUPERVISOR

DATE 2-14-90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 10/29/91

*See Instructions on Reverse Side

Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the
fictitious or fraudulent statements or representations as to any matter within its jurisdiction.