

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

<p>SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.</p>		
<p>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		
<p>1. Name of Operator Jonh S. Goodrich</p>		7. Unit Agreement Name
<p>2. Address of Operator 4000 N. Big Spring, Suite #109, Midland, Texas 79705</p>		8. Farm or Lease Name Martha Forrest
<p>3. Location of Well UNIT LETTER <u>M</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>0</u> FEET FROM THE <u>West</u> <u>SW/4 SW/4</u> LINE, SECTION <u>24</u> TOWNSHIP <u>25S</u> RANGE <u>36E</u> NMPM.</p>		9. Well No. 2
		10. Field and Pool, or Wildcat Jal Mat T-Y-SR
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		12. County Lea

<p>6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input checked="" type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/25
CIBP @ 3400' with 35' cement.
Displace hole with salt gel.
Pull 7" 50' plug in and 50' out of cut point.
Pull or perf 9 5/8" @ 500' cement with 100 sx.
10 sx & surface marker.
Clean location.

8 5/8 - 100 - 609-509

PULL 5 1/2 - 100' PLUG 1/2 in & out of cutpoint

ILLEGIBLE

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. M. Parker TITLE Agent DATE 4-15-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE APR 13 1988

CONDITIONS OF APPROVAL, IF ANY: