

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Brown	
9. Well No. 4	
10. Field and Pool, or Wildcat Jalmat	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator Apollo Oil Company	
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N. M. 88240	
4. Location of Well UNIT LETTER F , 1690 FEET FROM THE North LINE AND 1870 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 25 S RANGE 36 E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3049	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandon as follows:

Set cast iron bridge plug @ 3000 & cap with 35' cement
Cut & pull 5½" casing from 2000'
Spot 100' plug across 5½" casing stub
Spot 100' plug across top of salt @ 1350
Spot 100' plug across 8 5/8" casing shoe @ 557

10 sacks at surface with regulation marker
Mud between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Wesley Hollis</i></u>	TITLE <u>Agent</u>	DATE <u>2/5/74</u>
APPROVED BY <u>Orig. Signed by</u>	TITLE <u>SEE 8 MAR</u>	DATE <u>SEE 8 MAR</u>
CONDITIONS OF APPROVAL, IF ANY: <u>None</u>		