ſ	-		
NO. OF COPIES RECEIVED	•		Free C. Lon
DISTRIBUTION			Form C-103 Supersedes Old
SANTA FE		DNSERVATION COMMISSION	C-102 and C-103
FILE		COMMISSION	Effective 1-1-05
U.S.G.S.	1		·
LAND OFFICE			Sa. Indicate Type of Lease
OPERATOR	- · ·		State Fee X
]		5. State Oll & Gas Lease No.
		· · · · · · · · · · · · · · · · · · ·	
LOO NOT USE THIS FORM FOR PAC	RY NOTICES AND REPORTS (DPOSALS TO DRILL OR TO DEEPEN OF PLU ION FOR PERMIT - " (FORM C-101) FOR	ON WELLS	
USE "APPLICAT	ION FOR PERMIT -** (FORM C-101) FOR	JG BACK TO A DIFFERENT RESERVOIR. SUCH PROPOSALS.)	
			7. Unit Agreement Name
WELL X WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
Maralo, Inc.			Humphreys
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·		
P. O. Box 832, Midland, Texas 79702 0832			9. Well No. 2
4. Location of Well			
UNIT LETTER K	1650 South	2210	10. Field and Pool, or Wildcat
	1650 FEET FROM THE South	LINE AND FEET	Jalmat-Tansill Yates-S.R.
THE LINE, SECTIO	N TOWNSHIP	84NGEN	
mmmmmmmm	· · · · · · · · · · · · · · · · · · ·		
	15. Elevation (Show wheth	er DF, KT, GR, etc.)	12. County
			Lea ()))))))
Check A	appropriate Box To Indicate	Nature of Notice, Report or	
NOTICE OF IN	TENTION TO:	Nathe of Notice, Report or	Other Data
		SUBSEQU	ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON		
TEMPORARILY ABANDON	PLUG AND ABANDON		ALTERING CASING
PULL OR ALTER CASING	F	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	CHANGE PLANS	CASING TEST AND CEMENT JOB	
OTHER		отнея Р	lug Back
· · ·			
7. Describe Proposed or Completed Ope	rations (Clearly state all pertinent d		ling estimated date of starting any proposed
work) SEE RULE 1103.	i source and permit at the	iuiis, and give pertinent dates, includ	ling estimated date of starting any proposed
5-6-86 RUPU - Remove equ	ipment. Ran CBL/GR 3163	3-2700' and CET/GR 3254-	2282
Formation Tops:	Rustler	1033	2202.
	Salt	1242	
	Yates	29.37	
· · ·	Seven Rivers	3175	
5-11-86 PU 5 1/2" RTTS p	kr & RTH on 83 its 2 2/		
5-11-86 PU 5 1/2" RTTS pkr & RIH on 83 jts 2 3/8" tbg. & set @ 2453'. Tried to load 5 1/2" csg; would not load. Released pkr. POH to 500' reset pkr. Burned (0 PUL)			
would not load. Released pkr. POH to 500', reset pkr. Pumped 60 BW dwon 5 1/2" csg; blow on 10 3/4" csg. but no fluid to surface. POH. LD pkr & SD.			
5-13-86 PU retrieveable BP & RTTS pkr. BIN on 84 (1) o o (1)			
5-13-86 PU retrieveable BP & RTTS pkr. RIN on 84 jts 2 3/8" tbg & set BP @ 2469'. Set pkr. @ 2464'. Tested BP to 1500 psi, ok. POH. Reset pkr @ 1275', had bad leak in csg between 1275 and 2464'. RIH w/pkr and reset @ 1871', had small loak PIU & most in Csg between 1275 and			
2464'. RIH w/pkr and reset @ 1871' had amalling a mail in a mail i			
2464'. RIH w/pkr and reset @ 1871', had small leak. RIH & reset pkr @ 2168', had small leak. RIH & reset pkr @ 2464' - still had small leak. (Num leak)			
RIH & reset pkr @ 2464' - still had small leak. (Pkr leaking). Dropped down and picked up RBP. POH w/84 jts. tbg, SN, pkr, retrieveable BP. LD same. RIH w/5 1/2" Howco easy drill retainer on 83 jts. 2 3/8" tbg. to 2454'. SDFN			
83 jts. 2 3/8" tbg. to 24		D same. RIH w/5 1/2" How	co easy drill retainer on
5-14-86 SEt cmt retainer	a 2454' on $83 + a 24$	011 +1 - 0	
5-14-86 SEt cmt retainer gilsonite/sx + 2% CaCl2 &	100 ev Class C emb	of the Squeezed w/100 s	x Class "C" cement w/3#
<pre>gilsonite/sx + 2% CaCl2 & retainer, left 63' cmt.</pre>	n top of retainer Do	/2% CaCl2. Squeezed @ 9	50 psi. Pulled out of
5 1/2" csg. four times 13 Thereby certify that the information abo			Had bad leak @ 2158',
	not and complete to the best o	I my knowledge and belief.	
K. A. (M			CONTINUED ON ATTACHED
NED LIENA Offin	TITLE	Agent	5-19-87
Orig. Signed by	4-744/		UAIL
Paul Kautz			
Geologist			
DITIONS OF APPROVAL, IF ANY:			- PATEMAY 2 1 1987-
V 10			
ĸ			

2187 & 2276'. Dropped standing valve. Pressured tbg, but would not hold. Tagged TD @ 2281'. POH. SDFN 5-15-86 PU pkr & RIN on 2 3/8" tbg. to 2276'. Tested tbg to 6000 psi above slips GIH. Found 1 pin hole in tbg., 1 collar leak & busted 2 jts tbg. Set pkr @ 2276'. Tested to 1000 psi, ok. Tested 5 1/2" csg, set pkr from 2276' back up to 770', csg. ok. Found leak in 5 1/2" csg between 525' - 770'. POH. LD pkr. RIH w/ 4 5/8" bit on 6-3 1/2" DC's, 20 jts 2 3/8" tbg. SDFN 5-16-86 Finish RIH w4 5/8" bit & 6-3 1/2" DC's on 71 jts 2 3/8" tbg to top of fill @ 2275'. Drld and circ'd hole clean to BP @ 2454'. Drld out BP & good cement to 2533', 258' total. Circ'd hole clean. SDFN 5-17-86 Drilled good cmt. from 2533-2842'. Circ'd hole clean. Did not feel bad place in csg. 5-18-86 Drld. good cmt from 2842-3165'. Circ'd hole clean. Left 10' of cmt on top of BP. Drld 323'. Drld total of 890' cmt. LD swivel. POH w/tbg & LD DC's & bit. 5-20-86 RU Schlumberger. Ran Comp. Neutron Log. RIH w/3 3/8" perf gun. 5-21-86 Shot 30 holes in 3 runs, perf'd w/1 JSPF @ 2947', 2952', 2960', 2964', 2968', 2971', 2980' 2990', 2994', 2996', 2998', 3000', 3005', 3010', 3039', 3044', 3051', 3059', 3083', 3085', 3094', 3112', 3115', 3125', 3131', 3138', 3140', 3142', 3144', 3153' (30 noles). Loaded tbg w/15% MCA triple inhibited acid, set across each perf and acidized 25 glas acid at each perforation. Pumped in W 1600 psi. POH to 2367', pumped wtr down 5 1/2" csg to clear all acid. Set pkr on 97 jts. Pressured to 300 psi, ok. 5-23-86Loaded and pressed 5 1/2" csg to 200 psi, ok. Started treatment. Pumped 6,500 gals 40# gelied 2% KUL pad, /,500 gals 40# gelied wtr. w/1# 20/40 sand/gal. Pumped 1000 gals gelled wtr., dropped 10 ball sealers. 200 psi increase in press w/balls on formation. Pumped /,500 gals gelied 2% KCL w/2# 20/40 sand. Pumped 1000 gals gelied 2% KCL, dropped 10 ball sealers. Had 400 psi increase w/balls on formation. Pumped /500 gal gelled 2% KCL w/3# 20/40 sand. Flushed to btm perf w/2% KCL. ISDP 1100 psi, 5 min 960 psi, 10 min 920 psi, 15 min 910 psi. Formation broke @ 2000 psi. Max press 3600 psi, avg injection rate 14 BPM @ 3400 psi. 5-24-8/ Well SI 19 hrs for gel to break. 5-30-86 ollo PBTD. well pumping 0 s0 = 20 Bw FDrU. 0-24-8τ In ∠4 hrs. pumped 3 BO + 12 BW + 34 MCF . Operation to fracture treat Yates perforations