(May 1963)		INT OF THE INTER	IOR (Other instructions o.	Budget Burg 5. LEASE DESIGNATION	80-No. \$2-R1424.	
GEOLOGICAL SURVEY					A.G.Falby LC032715	
	·····	6. IF INDIAN, ALLOTTI				
	INDRY NOT					
<u>.</u>	Use "APPLICA"	TION FOR PERMIT—" for such p	roposals.)			
OIL GAS		7. UNIT AGREEMENT N	· · · · ·			
2. NAME OF OPERATOR		Cooper Jal 8. FARM OB LEASE NA				
Reserve O	il and Gas (Cooper Jal	2 \			
3. ADDRESS OF OPERA		9. WELL NO.				
First Savin	ng s Bu ild ing	220				
4. LOCATION OF WELL See also space 17 At surface	(Report location cl	10. FIELD AND POOL,	DR WILDCAT			
	0' FSL & 62	Jalmat 11. SEC., T., B., M., OB	DT F AVE			
Sec. 19, 2		SURVEY OR ARE				
500, 1 <i>7</i> , 1	10-011	19-24S-37E				
14. PERMIT NO.	·····	15. ELEVATIONS (Show whether DI	r, RT, GR, etc.)	12. COUNTY OR PARIS	H 13. STATE	
		3284 GR		Lea	New Mexico	
16.	Check An	propriate Box To Indicate N	Jature of Nation Parata			
	NOTICE OF INTEN			무 수 문 물		
			SUBS	BEQUENT REPORTIOF		
TEST WATER SHO	r-0 FF P	ULL OB ALTER CASING	WATER SHUT-OFF	REPAIRING	WILL	
FRACTURE TREAT		ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING	CARING	
SHOOT OR ACIDIZE Repair well	···	BANDON*	(Other) Convert t	o Water Injectio		
(Other)		HANGE PLANS		ilts of multiple completion		
17. DESCRIBE PROPOSED proposed work.	AL WELL IN MILECHUI	RATIONS (Clearly state all pertinen nally drilled, give subsurface loca	t details and give pertinent det	mpletion Report and Log fo tes, including estimated da tical depths for all marke	A	
				. 방문요한	1 J	
		e Jalmat zone of th	is well was authori	zed by NMOCC	Stronger 1	
Order No.	R-4020.					
To convert	; this well to	o water injection se	rvice, the following	g operations hav	ves the second	
been perfo					. M C - F	
					or polo r polo series lorig	
	, F				111 : 2 : 4 일 231 : 음 개 문 위	
2. Cleaned out well with sand pump from 3135' to 3200'.					Loco and an and an and an and an	
3. Ran 99 joints 2-3/8" cement-lined tubing and Baker Model AD						
tension packer. Set packer at 3008' with 16000# tension (Jalmat						
	zone perfs a	are 3060'-3158').				
4.	Placed inhil	bited fresh water al	ove packer in casin	ng annulus	· 영상 김 유민이 영국 김 영상 명령	
 Placed inhibited fresh water above packer in casing annulus Shut well in awaiting completion of injection facilities. 						
		· ·	U .	21013		
				dia di anti- anti- anti- anti-		
		Above work con	npleted August 27,	1971	227 34	
			-provou muguot bij	n and a start of the start of t		
				Sis Sis	월년 - 유통물일 3 위 : 동 명일 - 위	
18. I hereby certify th	at the foregoing is	True)and correct				
SIGNED	em,	Jule	District Manager	Septe	mber 13, 1971	
(This space for F	ederal or State offic					
APPROVED BY _ CONDITIONS OF	APPROVAL, IF A					
	· · · · · · · · · · · · · · · · · · ·					
			I SEP	1 5 1971		
*See Instructions on Reverse Side S. GEOLOG				0000		
			HORRE	NGIGAL SURVEY		
				NEW MEXICO		



SEP 2 11971 OIL CONSERVATION COMM. HOBBS, N. M.